





No plant or equipment exceeding the assessed 3 tonne GVW capacity of the structure is to traverse the bridge deck.



- Notes**
1. This drawing is not to be used in whole or part other than for the intended purpose and project, as defined on this drawing. Refer to the Contract for the full terms and conditions. This drawing should be read in conjunction with drawing no.'s B38380DE-FK-0001, 0001a & 0002.
 2. All dimensions are in millimetres and levels in metres unless otherwise stated. Dimensions are based on site measurements taken during a site investigation and historical information provided by HRE. Buckle plate thickness was confirmed throughout the soffit at locations where plates are subject to various states of corrosion using a UT gauge.
 3. Locations and extent of services are indicative only and not exhaustive. Contractor to confirm exact location, nature and owner of any services within the area affected by the permanent or temporary works.
 4. The defects shown are based on an inspection survey undertaken by Jacobs on 28/11/2022 and a detailed examination report provided by HRE. Additional defects are likely to be identified following grit blasting works. It is recommended that an additional defect survey is carried out with the Contractor in advance of the works commencing to identify any further deterioration of existing defects and confirm the repair requirements. A tactile inspection of defective areas should be undertaken at the commencement of the works on site. The Contractor remains responsible for establishing the exact dimensions and materials of the members to be replaced.
 5. To ensure repairs can be completed to appropriate quality levels and to prevent any contamination from the existing paint system, the areas of the works proposed to be painted and grit blasted should be scaffolded and fully encapsulated.
 6. Heavily corroded steel to be cut out and replaced with new S355 steel. Replacement steel to be welded to the existing elements by a 6mm thick butt or fillet weld connection.

Holed metallic elements are to be over-plated with new S355 steel. Corroded material surrounding the hole should be cut out prior to repairing.

Heavily corroded rivets to be removed and replaced with dome headed HSFG bolts with the same diameter and similar appearance to the original.
 7. Metallic classification undertaken as part of a 2004 site investigation confirmed that the footbridge is constructed from weldable mild steel. A unit weight of 7850kg/m³ is assumed for structural steel as per by the Specification for Highway Works.
 8. Testing of paint samples confirmed that the existing paint system contains lead. All works are to be undertaken in accordance with Control of Lead at Work Regulations 2002.
 9. All replaced steel will be painted to match the existing colour identified by testing paint samples during the site investigation (RAL 7024- 'Graphite Grey'). The appearance of the structure will therefore remain unchanged following the works. All existing metallic elements of the structure, will be grit blasted to remove corrosion and a new paint system will be applied. A Type I (M) paint system as per the Specification for Highway Works, Series 5000 is required.





Legend

- Full section loss
- Moderate section loss
- New dome headed HSFG bolt

Key

HEALTH, SAFETY AND ENVIRONMENTAL BOX	
In addition to the hazards/risk normally associated with the types of work detailed on this drawing, note the following:	
DESCRIPTION OF HAZARD	
1	Poor condition of the structure. Hidden defects resulting in local failure of elements.
2	Existing metallic paint system contains lead.
5	Understrength structure.
CONSTRUCTION RISKS	
In addition to the hazards/risk normally associated with the types of work detailed on this drawing, take note of the above. It is assumed that all works on this drawing will be carried out by a competent contractor working, where appropriate, to an appropriate method statement. Details of the design mitigation measures and residual risks are contained within the HERRR.	



**Individual existing rivets that need replacement should be removed and replaced out of sequence. Every second rivet in a single row should be replaced before going back and replacing the alternate rivets. Hence, adjacent bolts are not removed consecutively during the replacement process

02	31/07/2023	For Construction	■	■	■	■
01	31/07/2023	Revised Form B	■	■	■	■
Rev	Rev. Date	Purpose of revision	Orig	Check'd	Rev'd	Apprv'd

Jacobs
20 GEORGE HUDSON STREET, York, YO1 6WR
Tel: +44 (0)1904 924 950
WEBSITE: WWW.JACOBS.COM

Client: Historical Railways Estate on behalf of the DfT

Project: HRE Works Framework

Drawing title: STRUCTURE AGB/3
STRUCTURAL REPAIRS
PROPOSED REPAIR DETAILS

Drawing status: FOR CONSTRUCTION Suitability

Scale: AS NOTED @ A1 DO NOT SCALE

Jacobs No. B38380DE Rev

Client No. AGB/3 02

Drawing number: B38380DE-FK-0002a

© Copyright 2023 Jacobs U.K. Limited. The concepts and information contained in this document are the property of Jacobs. Use or copying of this document in whole or in part without the written permission of Jacobs constitutes an infringement of copyright. Limitation: This drawing has been prepared on behalf of, and for the exclusive use of, Jacobs Clients, and is subject to, and issued in accordance with, the provisions of the contract between Jacobs and the Client. Jacobs accepts no liability or responsibility whatsoever for, or in respect of, any use of, or reliance upon, this drawing by any third party.