job_number	site_code	plot_number	job_log_number	job_entry_date	job_notes	job_location	job_status_flag	customer_code	price_factor_code	job_complete_date	job_easting	job_northing	order_number	priority_code	actual_comp_date	contract_area_code	customer_reference	job_start_date	contract_name	cost_code_name	logged_date	follow_up_date	follow_up_code	log_effective_date	feature_location	feature_id	site_name	feature_type_name	status_name	contract_area_name	survey_obs_start	survey_obs_end	area_code	ward_code	actual_start_date	target_comp_date	job_type_name	parent_job_number	hazard_type_key	hazard_type_name	param_type_name
49440636	MD09002153	80005003	11	12/12/2024 09:46	Large Tree has fallen across the hard shoulder completely obstructing the hard shoulder. This has now been cut back behind the barrier by inspector, no further action required at this stage. (Environmental Defect (Points))	A38M D-C Link just after Lamp column number DC28	C	HE	FNOW	12/12/2024 09:47	409222.5	290248.5	62503248	FNOW	12/12/2024 09:47	A09		12/12/2024 09:46:52:437	Fix Now - Internal	Fix Now - Internal	07/03/2025 14:05	07/03/2025 13:56:53:55	NCA	07/03/2025 13:56:53:55			4600A38M/33	TR: Tree Risk Recording	Post Compl Inspection Passed	Highways England Area 9			9665	WM02	12/12/2024 09:46	12/12/2024 09:47	B Reim Soft Estate Landscape		4	Schedule B	M&R: Type of Repair
49440693	MD09002153	80005003	3	13/12/2024 09:02	Large Tree has fallen in Storm Darragh. This has now been cut back behind the barrier by inspector. Remove remaining multi stem tree and ecoplug stumps. Remove all arisings, logs etc from site. (Environmental Defect (Points))	A38M D-C Link just after Lamp column number DC28	U	HE	R		409222.5	290248.5		28DY		A09			Area 9 - Schedule D	AD9 SchC&D Reactive M&R	23/02/2025 20:53	23/02/2025 20:46	NCA	23/02/2025 20:46			4600A38M/33	TR: Tree Risk Recording	Work Suspended	Highways England Area 9			9665	WM02			B Reim Soft Estate Landscape	49440636	4	Schedule B	M&R: Type of Repair
49441047	MD09002151	2	13	19/12/2024 09:00	F TO LINK POTHOLE BETWEEN LAMP COLUMN F 13 AND FC14 POTHOLE IN LANE 1 (Pavement Defect)	F TO LINK POTHOLE BETWEEN LAMP COLUMN F 13 AND FC14 POTHOLE IN LANE 1	A	HE	R	20/12/2024 09:17	409588.6	290169.3	62643541	24HC	20/12/2024 10:19	A09		20/12/2024 08:32	Area 9 - Schedule C	AD9 SchC&D Reactive M&R	15/01/2025 17:58			15/01/2025 17:58	A38M Southbound. (FC Link). From Tyburn Road to Merge DC.	4600A38M/27	4600A38M/27	Dual 1-Lane	Job Closed	Highways England Area 9	284.71	284.71	9665	WM02	20/12/2024 10:06	20/12/2024 10:20	B Reim Pavements / Paved Areas		4	Schedule B	M&R: Type of Repair
49441077	MD09002155	260034	11	19/12/2024 11:15	Out of City towards Erdington. Approximately 90m past mp A38 approaching the end of our section, Access Cover/ Gully Lid in the Centre Res have collapsed/missing. Just past Lamp Column DC03. This was covered with a cover plate but the plate is now not over the gully. ZRT to pull up over back over the grate to make safe. (Drainage Defect)	A5127 (A38m) Out of City towards Erdington, C/Res.	A	HE	R	20/12/2024 10:11	409847.6	290309.5	62643566	24HC	20/12/2024 09:48	A09		20/12/2024 09:26	Area 9 - Schedule C	AD9 SchC&D Reactive M&R	15/01/2025 17:58			15/01/2025 17:58	A5127		4600A5127/22	Gully	Job Closed	Highways England Area 9			9666	WM02	20/12/2024 09:44	20/12/2024 11:15	B Reim Drainage, Service Ducts		2	Drainage	M&R: Asset Status Def & Maint
49441254	MD09002149	2	12	23/12/2024 09:40	X1 Pothole in the nearside of lane 2, ZRT to make safe defect score 15. (Pavement Defect)	A38M C-F link nearside of lane 2, near lamp column number FC14.	A	HE	R	24/12/2024 01:37	409614.2	290231.6	62643695	24HC	24/12/2024 09:25	A09		24/12/2024 00:52	Area 9 - Schedule C	AD9 SchC&D Reactive M&R	15/01/2025 17:59			15/01/2025 17:59	A38M Northbound. (CF Link) From start of slip road CD to NIS Node 460535213	4600A38M/24	4600A38M/24	Dual 2-Lane or one-way 2-Lane	Job Closed	Highways England Area 9	371.16	371.16	9664	WM02	24/12/2024 01:28	24/12/2024 09:40	B Reim Pavements / Paved Areas		4	Schedule B	M&R: Type of Repair
49441260	MD09002150	680006	19	23/12/2024 10:01	Road narrows from the left sign pointing in the wrong direction, ZRT to turn back around and to tighten bolts. Defect score 15. (Sign Face Defect)	A38M C-F link next to lamp column number CF24	A	HE	R	27/12/2024 06:41	409804.1	290057.3	62643702	24HC	27/12/2024 08:43	A09		27/12/2024 05:56	Area 9 - Schedule C	AD9 SchC&D Reactive M&R	15/01/2025 17:59			15/01/2025 17:59			4600A38M/25	Sign Face	Job Closed	Highways England Area 9			9664	WM02	24/12/2024 01:08	27/12/2024 08:45	B Reim Traffic Sign/Road Marks		4	Schedule B	M&R: Type of Repair
49442026	MD09002154	780001	2	07/01/2025 18:59:11:81	IN: Damage Safety Fencing/Barr - TO cam across barrier damage (Enquiry 19019182)	salford to m6 nb at the very start of salford as the bypass goes over the top	U	HE	R		0	0		R		A09	2395-070125			AD9 SchC&D Reactive M&R	08/01/2025 01:51:21:397	08/01/2025 01:51		08/01/2025 01:51			4600A5127/21	Safety Barrier (Steel)	Job Cancelled	Highways England Area 9			9666	WM02			A Lmp Incident Response		5	Incident	DCP:Claim Status
49442089	MD09002151	2	7	08/01/2025 10:42	F TO C LINK POTHOLE BY LAMP COLUMN FC 14 (Pavement Defect)	F TO C LINK POTHOLE BY LAMP COLUMN FC 14	A	HE	R	09/01/2025 10:42	409630.2	290156	62644434	24HC	08/01/2025 12:40	A09			Area 9 - Schedule C	AD9 SchC&D Reactive M&R	16/02/2025 20:48			16/02/2025 20:48	A38M Southbound. (FC Link). From Tyburn Road to Merge DC.	4600A38M/27	4600A38M/27	Dual 1-Lane	Job Closed	Highways England Area 9	241.16	241.16	9665	WM02	08/01/2025 12:33	09/01/2025 10:42	B Reim Pavements / Paved Areas		4	Schedule B	M&R: Type of Repair
49442214	MD09002154	2	11	09/01/2025 09:13	c to d link pothole in lane 1 by lamp column CD23 offside wheel track of lane 1. (Pavement Defect)	A38M C to D link pothole in lane 1 by lamp column CD23	A	HE	R	09/01/2025 22:39	409458.9	290218.3	62644499	24HC	10/01/2025 03:01	A09		09/01/2025 21:54	Area 9 - Schedule C	AD9 SchC&D Reactive M&R	16/02/2025 20:49			16/02/2025 20:49	A5127 Northbound. (CD Link). From CF Link to NIS node	4600A5127/21	4600A5127/21	Two Way Single 2-Lane C/way	Job Closed	Highways England Area 9	217.87	217.87	9666	WM02	10/01/2025 01:56	10/01/2025 09:13	B Reim Pavements / Paved Areas		4	Schedule B	M&R: Type of Repair