

INSPECTION RECORD SHEET

Route Ref.	3		Vehicle Reg	[REDACTED]						
Inspection Start	Date:	27/01/26	Inspection Finish	Date:	27/01/26	Inspection carried out by:	1)	[REDACTED]		
	Time:	0700		Time:	17:15		2)	[REDACTED]		

Sheet 1 of 7

All Safety Critical defects are to be reported to the ROC upon identification

Time	Road	Carriageway N/B, S/B, E/B, W/B	Location (MP, Jct)	Defect Number	Roc Log	Observations / Comments	Action		
							Defect Type Safety/Non- Safety	Time completed	Date Completed
10:40	M6	N/B	213/9 JCT 12 TO JCT 13	4947.197		X1 POTHOLE OFFSIDE LANE TWO	SAFETY		
10:45	M6	N/B	215/0+20 JCT 12 TO JCT 13	49473202		X1 POTHOLE NEARSIDE LANE THREE + X1 POTHOLE OFFSIDE LANE THREE.	SAFETY		
10:45	M6	N/B	216/1+60 JCT 12 TO JCT 13	49473206		X1 POTHOLE OFFSIDE LANE TWO	SAFETY		
10:55	M6	N/B	220/0 TO 220/1 JCT 13 BETWEEN THE SLIPS	49473219		X3 POTHOLES / DEPRESSIONS NEARSIDE LANE ONE	SAFETY		
11:05	M6	N/B	226/4 + 50 DOXEY EXIT SLIP	49473233		X2 POTHOLES ON CENTRE OF JOINT LINE	SAFETY		
11:15	M6	N/B	DOXEY ENTRY SLIP ADJACENT TO D.V.S.A WEIGHBRIDGE	49473239		X1 POTHOLE CENTRE LINE LANES ONE & TWO	SAFETY		
11:35	A38/ M6	N/B	JCT 14 ROUNDABOUT JUST AFTER N/B EXIT	49473250		X1 POTHOLE AROUND GULLY NEARSIDE LANE ONE	SAFETY		
11:40	M6	N/B	234/8 ADJACENT TO STAFFORD SERVICES EXIT SLIP	49473256		X1 POTHOLE OFFSIDE LANE TWO	SAFETY		
11:45	M6	N/B	239/8 YARNFIELD TO JCT 15	49473259		X1 POTHOLE OFFSIDE LANE TWO	SAFETY		

Inspection Lead:

[REDACTED]

Signature:

[REDACTED]

INSPECTION RECORD SHEET

Sheet 2 of 7

Route Ref.	3		Vehicle Reg	[REDACTED]		Inspection carried out by	1) [REDACTED] 2) [REDACTED]	
Inspection Start	Date:	27/01/26	Inspection Finish	Date:	27/01/26			
	Time:	0700		Time:	17:15			

All Safety Critical defects are to be reported to the ROC upon identification

Time	Road	Carriageway N/B, S/B, E/B, W/B	Location (MP, Jct)	Defect Number	ROC Log	Observations / Comments	Action		
							Defect Type Safety/Critical Safety	Time Completed	Date Completed
11:45	M6	N/B	243/7 YARNFIELD TO JCT 15	49473262		X1 POTHOLE NEARSIDE LANE ONE	SAFETY		
11:50	M6	N/B	244/1 + 70 YARNFIELD TO JCT 15	49473263		X1 POTHOLE OFFSIDE LANE TWO	SAFETY		
12:00	M6	N/B	JCT 15 EXIT SLIP	49473265		X2 POTHOLES NEARSIDE LANE ONE	SAFETY		
12:05	M6	N/B	JCT 15 EXIT SLIP TOWARDS TRAFFIC LIGHT'S	49473267		X1 POTHOLE CENTRE LINE LANES ONE & TWO	SAFETY		
12:10	M6	N/B + S/B	EXIT SLIP LINK ROAD TO JCT 15 R/BOUT	49473269		X1 POTHOLE CENTRE LINE LANES TWO & THREE	SAFETY		
13:20	M6	N/B	JCT 15 ENTRY SLIP	49473300		X4 POTHOLES NEARSIDE LANE ONE	SAFETY		
13:20	M6	N/B	JCT 15 ENTRY SLIP	49473301		X1 POTHOLE IN LANE ONE	SAFETY		
13:25	M6	N/B	246/3 ADJACENT TO JCT 15 ENTRY SLIP	49473304		X1 POTHOLE CENTRE LINE LANES TWO & THREE	SAFETY		
13:25	M6	N/B	246/4 JCT 15 ENTRY SLIP	49473305		X1 POTHOLE OFFSIDE DN ENTRY SLIP	SAFETY		

Inspection Lead	[REDACTED]	Signature	[REDACTED]
-----------------	------------	-----------	------------

INSPECTION RECORD SHEET

Route Ref:	3		Vehicle Reg:	[REDACTED]		Inspection carried out by:	1) [REDACTED]
Inspection Start Date:	27/01/26	Inspection Start Time:	0700	Inspection Finish Date:	27/01/26		Inspection Finish Time:

Sheet 3 of 7

All Safety Critical defects are to be reported to the ROC upon identification

Time	Road	Carrageway N/B, S/B, E/B, W/B	Location (MP, Jct)	Defect Number	Roc Log	Observations / Comments	Action		
							Defect Type Safety/Non-Safety	Time completed	Date Completed
13:30	M6	N/B	246/5 +90 TOWARDS END JUNCTION 15 ENTRY	49473306		X2 POTHOLES CENTRE LINE LANES ONE & TWO	SAFETY		
13:30	M6	N/B	246/8+40 JCT 15 TO KEELE	49473307		X1 POTHOLE CENTRE LINE LANES ONE & TWO	SAFETY		
13:30	M6	N/B	246/9 + 50 JCT 15 TO KEELE	49473308		X1 POTHOLE CENTRE LINE LANES ONE & TWO	SAFETY		
13:35	M6	N/B	247/0 +40 TO 247/0 JCT 15 TO KEELE	49473309		X6 POTHOLES CENTRE LINE LANES ONE & TWO	SAFETY		
13:40	M6	N/B	248/9+10 JCT 15 TO KEELE	49473310		X1 POTHOLE IN CENTRE OF LANE ONE	SAFETY		
13:40	M6	N/B	248/9 + 80 JCT 15 TO KEELE	49473311		X1 POTHOLE CENTRE LINE LANES ONE & TWO	SAFETY		
13:40	M6	N/B	249/0+10 JCT 15 TO KEELE	49473312		X1 POTHOLE IN CENTRE OF LANE ONE	SAFETY		
13:40	M6	N/B	249/1 +20 JCT 15 TO KEELE	49473313		X1 POTHOLE NEARSIDE LANE TWO ON LOOPIS	SAFETY		
13:40	M6	N/B	249/3 +70 JCT 15 TO KEELE	49473315		X1 POTHOLE NEARSIDE LANE ONE	SAFETY		

Inspection Lead:	[REDACTED]	Signature:	[REDACTED]
------------------	------------	------------	------------

INSPECTION RECORD SHEET

Sheet 4 of 7

Route Ref	3		Vehicle Reg	[REDACTED]		Inspection carried out by:	1) [REDACTED] 2) [REDACTED]
Inspection Start	Date:	27/01/26	Inspection Finish	Date:	27/01/26		
	Time:	0700		Time:	17:15		

All Safety Critical defects are to be reported to the ROC upon identification

Time	Road	Carriageway N/B, S/B, E/B, W/B	Location (MP, Jct)	Defect Number	ROC Log	Observations / Comments	Action		
							Defect Type Safety/Non- Safety	Time completed	Date Completed
15:40	M6	N/B	256/8 KEELE TO JCT 16	49473334		X1 POTHOLE OFFSIDE LANE ONE	SAFETY		
15:40	M6	N/B	257/0+60 KEELE TO JCT 16	49473335		X1 POTHOLE NEARSIDE + X1 POTHOLE OFFSIDE ON H/S	SAFETY		
15:40	M6	N/B	257/2+70 KEELE TO JCT 16	49473337		X1 POTHOLE NEARSIDE LANE ONE	SAFETY		
15:40	M6	N/B	257/4+40 KEELE TO JCT 16	49473338		X1 POTHOLE NEARSIDE LANE ONE	SAFETY		
15:45	M6	N/B	257/9+50 KEELE TO JCT 16	49473339		X2 POTHOLES OFFSIDE ON H/S	SAFETY		
15:45	M6	N/B	258/0+50 KEELE TO JCT 16	49473340		X1 POTHOLE NEARSIDE LANE TWO	SAFETY		
15:50	M6	N/B	260/0+70 KEELE TO JCT 16	49473341		X2 POTHOLES OFFSIDE + X1 POTHOLE NEARSIDE ON H/S	SAFETY		
15:50	M6	N/B	260/1+90 KEELE TO JCT 16	49473342		X2 POTHOLES NEARSIDE LANE ONE	SAFETY		
15:50	M6	N/B	260/9 JCT 16 EXIT SLIP	49473343		X1 POTHOLE NEARSIDE LANE ONE	SAFETY		

Inspection Lead:

Signature:

INSPECTION RECORD SHEET

Route Ref	3		Vehicle Reg	[Redacted]		Inspection carried out by:	1) [Redacted] 2) [Redacted]	
Inspection Start	Date:	27/01/26	Inspection Finish	Date:	27/01/26			
	Time:	0700		Time:	17:15			

All Safety Critical defects are to be reported to the ROC upon identification

Time	Road	Carriageway N/B, S/B, E/B, W/B	Location (MP, Jct)	Defect Number	Roc Log	Observations / Comments	Action		
							Defect Type Safety/Non- Safety	Time Completed	Date Completed
16:20	M6	S/B	247/7+90 KEELE TO JCT 15	49473356		X1 POTHOLE NEARSIDE LANE ONE	SAFETY		
16:25	M6	S/B	246/7+10 ADJACENT TO START OF JCT 15 EXIT	49473358		X1 POTHOLE NEARSIDE LANE THREE.	SAFETY		
16:25	M6	S/B	246/6 ADJACENT TO JCT 15 EXIT SLIP	49473359		X1 POTHOLE IN LANE THREE ON LODP'S	SAFETY		
16:25	M6	S/B	246/5+50 ADJACENT TO JCT 15 EXIT SLIP	49473360		X1 POTHOLE NEARSIDE LANE THREE	SAFETY		
16:30	M6	S/B	241/7+20 JCT 15 TO YARNFIELD	49473361		X1 POTHOLE NEARSIDE LANE ONE.	SAFETY		
16:30	M6	S/B	240/9+50 JCT 15 TO YARNFIELD	49473362		HGV WHEEL IN C/RES LEANING ON CONCRETE WALL	SAFETY		
16:35	M6	S/B	232/6+40 YARNFIELD TO JCT 14	49473363		X1 POTHOLE NEARSIDE LANE ONE	SAFETY		
16:40	M6	S/B	229/7+10 YARNFIELD TO JCT 14	49473364		X1 POTHOLE OFFSIDE LANE THREE.	SAFETY		
16:40	M6	S/B	228/9+50 JCT 14 EXIT SLIP	49473365		HGV WHEEL NEARSIDE VERGE LEANING AGAINST PH TERMINAL	SAFETY		

Inspection Lead: [Redacted]

Signature: [Redacted]

INSPECTION RECORD SHEET

Route Ref.	3		Vehicle Reg	[REDACTED]		Sheet 7 of 7	
Inspection Start	Date:	27/01/26	Inspection Finish	Date:	27/01/26	Inspection carried out by:	1) [REDACTED]
	Time:	0700		Time:	17:15		2) [REDACTED]

All Safety Critical defects are to be reported to the ROC upon identification

Time	Road	Carriageway N/B, S/B, E/B, W/B	Location (MP, Jct)	Defect Number	Roc Log	Observations / Comments	Action		
							Defect Type Safety/Non- Safety	Time completed	Date Completed
16:40	M6	S/B	225/9+30 DOXEY TO JCT 13	49473366		X1 POTHOLE NEARSIDE LANE ONE (REFILL)	SAFETY		
16:40	M6	S/B	220/4+90 DOXEY TO JCT 13	49473367		X1 POTHOLE NEARSIDE LANE ONE (REFILL)	SAFETY		

Inspection Lead:	[REDACTED]	Signature:	[REDACTED]
------------------	------------	------------	------------