

# INSPECTION RECORD SHEET

Route Ref. 3	Vehicle Reg	Inspection Finish	Date: 3/2/26	Time:
Inspection Start	Date: 3/2/26	Time:	Inspection carried out by: 1) [Redacted] 2) [Redacted]	

**All Safety Critical defects are to be reported to the ROC upon identification**

Time	Road	Carriageway N/B, S/B, E/B, W/B	Location (MP, Jct)	Defect Number	Roc Log	Observations / Comments	Action	
							Defect Type Safety/Non-Safety	Time completed
	M6	N/B	213/5 JUN 12-13.	49474033		X2 POTHOLES IN LANE 1.	SAFETY	
	M6	N/B	215/6 JUN 12-13.	49474099		X1 POTHOLE IN LANE 1.	SAFETY.	
	M6	N/B	JUNCTION 14 NORTH ENTRY SLIP	49474101		X1 POTHOLE IN LANE 1 START OF ENTRY SLIP.	SAFETY.	
	M6	N/B	STAFFORD SERVICES ENTRY SLIP	49474102		X2 POTHOLES JUST AFTER "MOTORWAY" SIGN ON SERVICE'S ENTRY SLIP.	SAFETY.	
	M6	N/B	241/5 + 50 YARN-FIELD - JUN 15.	49474104		X1 POTHOLE IN LANE 1.	SAFETY.	
	M6	N/B	250/1 + 50 JUN 15 - KEELE	49474105		X1 POTHOLE IN LANE 1	SAFETY.	
	M6	N/B	257/4 KEELE - JUN 16.	49474106		X1 POTHOLE IN LANE 1 NEAR - SIDE	SAFETY.	
	M6	N/B	258/0 KEELE - JUN 16.	4947107		X1 POTHOLE IN LANE 2.	SAFETY.	

Inspection Lead: [Redacted]

Signature: [Redacted]

~~PLEASE DO NOT WRITE~~  
~~PLEASE DO NOT WRITE~~  
~~PLEASE DO NOT WRITE~~

