

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Locality:

Area: No code allocated

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	2800A45/166 - A45 / NB / END OF WELLINGBOROUGH ENTR	Feature Type:	Dual 2-Lane or one-way 2-Lane		Area: R23WA 13 NS	
Batch:	82937320 - Inspection Batch			Route:	A45 Safety Inspection			Date: 28/01/2026
	No actionable defects found							
Batch:	82934485 - Inspection Batch			Route:	A45 Safety Inspection			Date: 21/01/2026
	No actionable defects found							
Batch:	82930327 - Inspection Batch			Route:	A45 Annual Litter Survey			Date: 16/01/2026
	No actionable defects found							
Batch:	82929441 - Inspection Batch			Route:	A45 Safety Inspection			Date: 14/01/2026
	No actionable defects found							
Batch:	82924632 - Inspection Batch			Route:	A45 Safety Inspection			Date: 07/01/2026
	No actionable defects found							
Batch:	82921540 - Inspection Batch			Route:	A45 Safety Inspection			Date: 31/12/2025
	No actionable defects found							
Batch:	82921438 - Inspection Batch			Route:	A45 Safety Inspection			Date: 24/12/2025
	No actionable defects found							
Batch:	82920436 - Inspection Batch			Route:	A45 Safety Inspection			Date: 17/12/2025
	No actionable defects found							
Batch:	82916442 - Inspection Batch			Route:	A45 Safety Inspection			Date: 10/12/2025
	No actionable defects found							
Batch:	82912673 - Inspection Batch			Route:	A45 Safety Inspection			Date: 03/12/2025
	No actionable defects found							
Batch:	82909403 - Inspection Batch			Route:	A45 Safety Inspection			Date: 28/11/2025
	No actionable defects found							
Batch:	82906891 - Inspection Batch			Route:	A45 Safety Inspection			Date: 19/11/2025
	No actionable defects found							
Batch:	82902740 - Inspection Batch			Route:	A45 Safety Inspection			Date: 12/11/2025
	No actionable defects found							
Batch:	82898258 - Inspection Batch			Route:	A45 Safety Inspection			Date: 05/11/2025
	No actionable defects found							
Batch:	82892283 - Inspection Batch			Route:	A45 Safety Inspection			Date: 29/10/2025
	No actionable defects found							
Batch:	82891354 - Inspection Batch			Route:	A45 Victoria Park to Wellingbo			Date: 27/10/2025
	No actionable defects found							
Batch:	82885960 - Inspection Batch			Route:	A45 Safety Inspection			Date: 22/10/2025
	No actionable defects found							
Batch:	82878294 - Inspection Batch			Route:	A45 Safety Inspection			Date: 15/10/2025
	No actionable defects found							

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: 2800A45/166 - A45 / NB / END OF WELLINGBOROUGH ENTR		Feature Type: Dual 2-Lane or one-way 2-Lane			Area: R23WA 13 NS	
Batch:	82868622 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 08/10/2025
Batch:	82865693 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 01/10/2025
Batch:	82865691 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 01/10/2025
Batch:	82862672 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 24/09/2025
Batch:	82853766 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 17/09/2025
Batch:	82845168 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 11/09/2025
Batch:	82836716 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 03/09/2025
Batch:	82828319 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 27/08/2025
Batch:	82824075 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 20/08/2025
Batch:	82812512 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 13/08/2025
Batch:	82804811 - Inspection Batch No actionable defects found			Route: A45 Safety Inspection				Date: 06/08/2025
Asset:	40,000.00	Asset - Locn.:		Feature Type: Non-Carriageway Surface			Area: R23WA 13 NS	
Batch:	82896718 - Inspection Batch No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset:	50,000.00	Asset - Locn.:		Feature Type: Non-Carriageway Surface			Area: R23WA 13 OS	
Batch:	82891289 - Inspection Batch No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset:	50,001.00	Asset - Locn.:		Feature Type: Non-Carriageway Surface			Area: R23WA 13 OS	
Batch:	82892365 - Inspection Batch No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 30/10/2025
Asset:	50,002.00	Asset - Locn.:		Feature Type: Non-Carriageway Surface			Area: R23WA 13 OS	
Batch:	82891388 - Inspection Batch No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset:	50,003.00	Asset - Locn.:		Feature Type: Non-Carriageway Surface			Area: R23WA 13 OS	
Batch:	82896850 - Inspection Batch No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 50,004.00	Asset - Locn.:			Feature Type: Non-Carriageway Surface			Area: R23WA 13 OS	
Batch: 82892367 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 30/10/2025	
Asset: 50,005.00	Asset - Locn.:			Feature Type: Non-Carriageway Surface			Area: R23WA 13 OS	
Batch: 82891342 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 50,006.00	Asset - Locn.:			Feature Type: Non-Carriageway Surface			Area: R23WA 13 OS	
Batch: 82891444 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 50,007.00	Asset - Locn.:			Feature Type: Non-Carriageway Surface			Area: R23WA 13 OS	
Batch: 82891542 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Batch: 82891442 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 50,008.00	Asset - Locn.:			Feature Type: Non-Carriageway Surface			Area: R23WA 13 OS	
Batch: 82891351 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 83,000.00	Asset - Locn.:			Feature Type: Reference Marker			Area: R23WA 13 NS	
Batch: 82891362 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 83,001.00	Asset - Locn.:			Feature Type: Reference Marker			Area: R23WA 13 NS	
Batch: 82891385 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 83,003.00	Asset - Locn.:			Feature Type: Reference Marker			Area: R23WA 13 NS	
Batch: 82897054 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 83,004.00	Asset - Locn.:			Feature Type: Reference Marker			Area: R23WA 13 NS	
Batch: 82891268 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 83,006.00	Asset - Locn.:			Feature Type: Reference Marker			Area: R23WA 13 NS	
Batch: 82891397 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 83,007.00	Asset - Locn.:			Feature Type: Reference Marker			Area: R23WA 13 NS	
Batch: 82891409 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 83,008.00	Asset - Locn.:			Feature Type: Reference Marker			Area: R23WA 13 NS	
Batch: 82896808 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 83,009.00	Asset - Locn.:			Feature Type: Reference Marker			Area: R23WA 13 NS	
Batch: 82891356 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 83,010.00	Asset - Locn.:			Feature Type: Reference Marker			Area: R23WA 13 NS	
Batch: 82891346 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 83,011.00	Asset - Locn.:			Feature Type: Reference Marker			Area: R23WA 13 NS	
Batch: 82896892 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 150,003.00	Asset - Locn.:			Feature Type: Catch pit			Area: R23WA 13 OS	
Batch: 82896815 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 150,005.00	Asset - Locn.:			Feature Type: Catch pit			Area: R23WA 13 NS	
Batch: 82891285 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 150,006.00	Asset - Locn.:			Feature Type: Catch pit			Area: R23WA 13 OS	
Batch: 82897043 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 200,000.00	Asset - Locn.:			Feature Type: Ditch			Area: R23WA 13 NS	
Batch: 82891363 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 200,001.00	Asset - Locn.:			Feature Type: Ditch			Area: R23WA 13 NS	
Batch: 82891398 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,040.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891358 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,054.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891360 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,068.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82896949 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 260,070.00	Asset - Locn.: .			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82897061 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,071.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891355 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,072.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891353 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,073.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891352 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,074.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891350 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,075.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82897067 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,077.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891392 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,078.00	Asset - Locn.: .			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82896969 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,079.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891361 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,080.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891381 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,081.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891386 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,083.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891393 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 260,084.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891408 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,085.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891402 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,086.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82895694 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 31/10/2025
Asset: 260,087.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891389 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,088.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891543 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Batch: 82891440 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,089.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82891274 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,090.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891376 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,091.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891391 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,092.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82896959 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,093.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82896987 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,094.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82891280 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 260,095.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891333 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 260,096.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896810 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,097.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896784 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,098.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896769 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,099.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891293 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 260,100.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891311 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 260,101.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896946 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,102.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896943 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,103.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896936 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,104.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896917 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,105.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896867 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,106.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896860 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 260,107.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896847 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,108.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896828 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,109.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891357 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 260,110.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82897069 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 260,111.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891349 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 260,112.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891344 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 260,113.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891359 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 260,114.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891366 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 260,115.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82891421 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 260,117.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891399 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 260,118.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891556 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Batch: 82891437 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 260,119.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891401 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,120.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891400 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,121.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891374 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,122.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891404 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,123.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891377 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,124.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891338 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,125.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891341 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,126.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82891295 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,127.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896934 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,128.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896884 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,129.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82896870 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,130.00	Asset - Locn.:			Feature Type: Gully			Area: R23WA 13 OS	
Batch: 82895701 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 31/10/2025

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 260,131.00	Asset - Locn.: .			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82897073 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,132.00	Asset - Locn.: .			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82896996 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,133.00	Asset - Locn.: .			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82895689 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 31/10/2025
Asset: 260,134.00	Asset - Locn.: .			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82896773 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,135.00	Asset - Locn.: .			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82897018 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 260,136.00	Asset - Locn.: .			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82891282 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 260,137.00	Asset - Locn.: .			Feature Type: Gully			Area: R23WA 13 NS	
Batch: 82897014 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 290,000.00	Asset - Locn.: .			Feature Type: Inlet			Area: R23WA 13 NS	
Batch: 82891410 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 320,000.00	Asset - Locn.: .			Feature Type: Manhole			Area: R23WA 13 OS	
Batch: 82891375 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 320,001.00	Asset - Locn.: .			Feature Type: Manhole			Area: R23WA 13 NS	
Batch: 82891378 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 320,002.00	Asset - Locn.: .			Feature Type: Manhole			Area: R23WA 13 NS	
Batch: 82891390 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 320,003.00	Asset - Locn.: .			Feature Type: Manhole			Area: R23WA 13 NS	
Batch: 82895693 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 31/10/2025

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 320,004.00	Asset - Locn.: .			Feature Type: Manhole			Area: R23WA 13 NS	
Batch: 82897057 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 320,005.00	Asset - Locn.: .			Feature Type: Manhole			Area: R23WA 13 NS	
Batch: 82896957 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 320,006.00	Asset - Locn.: .			Feature Type: Manhole			Area: R23WA 13 OS	
Batch: 82895699 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 31/10/2025	
Asset: 320,008.00	Asset - Locn.: .			Feature Type: Manhole			Area: R23WA 13 NS	
Batch: 82895704 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 31/10/2025	
Asset: 450,000.00	Asset - Locn.: *			Feature Type: End Terminal			Area: R23WA 13 NS	
Batch: 82891318 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 450,001.00	Asset - Locn.: *			Feature Type: End Terminal			Area: R23WA 13 NS	
Batch: 82896862 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 450,002.00	Asset - Locn.: *			Feature Type: End Terminal			Area: R23WA 13 NS	
Batch: 82896839 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 450,003.00	Asset - Locn.: *			Feature Type: End Terminal			Area: R23WA 13 NS	
Batch: 82896743 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 500,000.00	Asset - Locn.: .			Feature Type: Hatched Road Marking			Area: R23WA 13 OS	
Batch: 82891417 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 540,000.00	Asset - Locn.: .			Feature Type: Kerb			Area: R23WA 13 OS	
Batch: 82896963 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 540,001.00	Asset - Locn.: .			Feature Type: Kerb			Area: R23WA 13 NS	
Batch: 82896716 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 540,002.00	Asset - Locn.: .			Feature Type: Kerb			Area: R23WA 13 NS	
Batch: 82896922 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 540,003.00	Asset - Locn.:			Feature Type: Kerb			Area: R23WA 13 NS	
Batch: 82896720 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 540,004.00	Asset - Locn.:			Feature Type: Kerb			Area: R23WA 13 NS	
Batch: 82891271 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 540,005.00	Asset - Locn.:			Feature Type: Kerb			Area: R23WA 13 OS	
Batch: 82891555 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Batch: 82891438 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 540,006.00	Asset - Locn.:			Feature Type: Kerb			Area: R23WA 13 OS	
Batch: 82891367 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 540,007.00	Asset - Locn.:			Feature Type: Kerb			Area: R23WA 13 NS	
Batch: 82891411 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 540,008.00	Asset - Locn.:			Feature Type: Kerb			Area: R23WA 13 OS	
Batch: 82896780 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,000.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 OS	
Batch: 82891550 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Batch: 82891434 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 570,001.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82896729 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,002.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82896749 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,003.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 OS	
Batch: 82891372 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 570,004.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82896793 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 570,005.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 OS	
Batch: 82897027 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,006.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 OS	
Batch: 82896763 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,007.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82897051 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,008.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82891324 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 570,009.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82896907 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,010.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82896754 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,011.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 OS	
Batch: 82896736 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,012.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82896817 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,015.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82897050 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,016.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82896721 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,017.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82896791 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,018.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82891369 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 570,019.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 OS	
Batch: 82896803 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,020.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82891553 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Batch: 82891431 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 570,021.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82891551 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Batch: 82891425 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 570,022.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 OS	
Batch: 82896915 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,023.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82891371 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 570,024.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82891328 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 570,025.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 NS	
Batch: 82896894 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 570,026.00	Asset - Locn.:			Feature Type: Longitudinal Road Marking			Area: R23WA 13 OS	
Batch: 82891301 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 660,000.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 OS	
Batch: 82897032 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 660,002.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82891552 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Batch: 82891424 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 660,003.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 OS	
Batch: 82891557 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Batch: 82891436 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 660,005.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82891554 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Batch: 82891427 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 660,006.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 OS	
Batch: 82891373 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 660,007.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82891370 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 660,008.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82891368 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 660,009.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 OS	
Batch: 82896800 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,010.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82896796 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,011.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82896897 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,012.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 OS	
Batch: 82896911 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,013.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82896903 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,014.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82891304 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 660,015.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82897024 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,016.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82896822 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,017.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82891309 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 660,018.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 OS	
Batch: 82891334 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 660,019.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82896725 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,020.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 OS	
Batch: 82896738 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,021.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82896732 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,022.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82896747 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,023.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 OS	
Batch: 82896759 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,024.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82896756 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 660,025.00	Asset - Locn.:			Feature Type: Road Stud			Area: R23WA 13 NS	
Batch: 82896788 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 680,000.00	Asset - Locn.:			Feature Type: Sign Face			Area: R23WA 13 NS	
Batch: 82891384 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 680,001.00	Asset - Locn.:			Feature Type: Sign Face			Area: R23WA 13 NS	
Batch: 82895690 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 31/10/2025
No actionable defects found								
Asset: 680,002.00	Asset - Locn.:			Feature Type: Sign Face			Area: R23WA 13 NS	
Batch: 82891364 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 680,003.00	Asset - Locn.:			Feature Type: Sign Face			Area: R23WA 13 NS	
Batch: 82891406 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 680,004.00	Asset - Locn.:			Feature Type: Sign Face			Area: R23WA 13 NS	
Batch: 82891403 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 680,005.00	Asset - Locn.:			Feature Type: Sign Face			Area: R23WA 13 NS	
Batch: 82891394 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 680,006.00	Asset - Locn.:			Feature Type: Sign Face			Area: R23WA 13 NS	
Batch: 82891347 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 690,000.00	Asset - Locn.:			Feature Type: Post (Signs)			Area: R23WA 13 NS	
Batch: 82891387 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 690,001.00	Asset - Locn.:			Feature Type: Post (Signs)			Area: R23WA 13 NS	
Batch: 82895691 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 31/10/2025
No actionable defects found								
Asset: 690,002.00	Asset - Locn.:			Feature Type: Post (Signs)			Area: R23WA 13 NS	
Batch: 82891383 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 690,003.00	Asset - Locn.:			Feature Type: Post (Signs)			Area: R23WA 13 NS	
Batch: 82891407 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 690,004.00	Asset - Locn.:			Feature Type: Post (Signs)			Area: R23WA 13 NS	
Batch: 82891396 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 690,005.00	Asset - Locn.:			Feature Type: Post (Signs)			Area: R23WA 13 NS	
Batch: 82891348 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 690,006.00	Asset - Locn.:			Feature Type: Post (Signs)			Area: R23WA 13 NS	
Batch: 82891365 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 690,007.00	Asset - Locn.:			Feature Type: Post (Signs)			Area: R23WA 13 OS	
Batch: 82891337 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 770,000.00	Asset - Locn.:			Feature Type: Verge			Area: R23WA 13 NS	
Batch: 82896869 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 770,001.00	Asset - Locn.:			Feature Type: Verge			Area: R23WA 13 NS	
Batch: 82895688 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 31/10/2025
Asset: 770,002.00	Asset - Locn.:			Feature Type: Verge			Area: R23WA 13 NS	
Batch: 82891379 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 770,003.00	Asset - Locn.:			Feature Type: Verge			Area: R23WA 13 NS	
Batch: 82891335 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 780,000.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82891336 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 780,001.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82891340 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 780,002.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896874 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
Asset: 780,003.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 OS	
Batch: 82895702 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 31/10/2025
Asset: 780,004.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82891339 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
Asset: 780,005.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 OS	
Batch: 82896831 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 780,006.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 OS	
Batch: 82891297 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 780,007.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896879 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,008.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82891343 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 780,009.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82891345 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 780,010.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82891380 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	
Asset: 780,011.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896919 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,012.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82897071 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,013.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82897059 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,014.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82897060 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,015.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82897010 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,016.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896782 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,017.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82891321 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 27/10/2025	

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 780,018.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896820 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,019.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82897003 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,020.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82897006 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,021.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896992 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,022.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896995 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,023.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896990 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,024.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896973 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,025.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896845 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,026.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896958 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,027.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896843 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,028.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896939 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	
Asset: 780,029.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896865 - Inspection Batch	No actionable defects found			Route: A45 Victoria Park to Wellingbo			Date: 03/11/2025	

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 780,030.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 13 NS	
Batch: 82896872 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 03/11/2025
No actionable defects found								
Asset: 788,001.00	Asset - Locn.:			Feature Type: Safety Barrier (Steel)			Area: R23WA 14 OS	
Batch: 82891545 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 790,000.00	Asset - Locn.:			Feature Type: Crossover			Area: R23WA 13 NS	
Batch: 82891287 - Inspection Batch				Route: A45 Victoria Park to Wellingbo				Date: 27/10/2025
No actionable defects found								
Asset: 1,030,044.00	Asset - Locn.: WE008/A - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,030,045.00	Asset - Locn.: WE008/B - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,030,046.00	Asset - Locn.: WE010/A - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,030,047.00	Asset - Locn.: WE010/B - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,030,048.00	Asset - Locn.: WE011/A - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 30/09/2025	
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 05/09/2025	
Asset: 1,030,049.00	Asset - Locn.: WE011/B - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 30/09/2025	
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 05/09/2025	
Asset: 1,030,050.00	Asset - Locn.: WE012/A - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 30/09/2025	
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 05/09/2025	
Asset: 1,030,051.00	Asset - Locn.: WE012/B - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 30/09/2025	
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 05/09/2025	
Asset: 1,030,052.00	Asset - Locn.: WE013/A - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 30/09/2025	
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 05/09/2025	
Asset: 1,030,053.00	Asset - Locn.: WE013/B - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,030,053.00	Asset - Locn.: WE013/B - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
	No actionable defects found							
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
	No actionable defects found							
Asset: 1,030,054.00	Asset - Locn.: WE014/A - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
	No actionable defects found							
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
	No actionable defects found							
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
	No actionable defects found							
Asset: 1,030,055.00	Asset - Locn.: WE014/B - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
	No actionable defects found							
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
	No actionable defects found							
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
	No actionable defects found							
Asset: 1,030,056.00	Asset - Locn.: IR071 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
	No actionable defects found							
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
	No actionable defects found							
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
	No actionable defects found							
Asset: 1,030,057.00	Asset - Locn.: IR072 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
	No actionable defects found							
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
	No actionable defects found							
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
	No actionable defects found							
Asset: 1,030,058.00	Asset - Locn.: IR073 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
	No actionable defects found							
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
	No actionable defects found							

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,030,058.00	Asset - Locn.: IR073 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,030,059.00	Asset - Locn.: IR074 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,030,060.00	Asset - Locn.: IR075 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,030,061.00	Asset - Locn.: IR076 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,030,062.00	Asset - Locn.: IR077 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,030,063.00	Asset - Locn.: IR078 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,030,064.00	Asset - Locn.: IR079 - WELLINGBOROUGH BYPASS E/BOUND			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 30/09/2025	
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 05/09/2025	
Asset: 1,030,065.00	Asset - Locn.: IR080 - WELLINGBOROUGH BYPASS E/BOUND			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 30/09/2025	
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 05/09/2025	
Asset: 1,030,066.00	Asset - Locn.: IR081 - WELLINGBOROUGH BYPASS E/BOUND			Feature Type: Lighting Unit			Area: No code allocated	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 30/09/2025	
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 05/09/2025	
Asset: 1,100,001.00	Asset - Locn.: WE008 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 30/09/2025	
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 05/09/2025	
Asset: 1,100,002.00	Asset - Locn.: WE010 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 30/09/2025	
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 05/09/2025	
Asset: 1,100,003.00	Asset - Locn.: WE011 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full			Date: 25/12/2025	

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,100,003.00	Asset - Locn.: WE011 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 30/09/2025
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 05/09/2025
Asset: 1,100,004.00	Asset - Locn.: WE012 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 25/12/2025
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 30/09/2025
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 05/09/2025
Asset: 1,100,005.00	Asset - Locn.: WE013 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 25/12/2025
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 30/09/2025
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 05/09/2025
Asset: 1,100,006.00	Asset - Locn.: WE014 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 25/12/2025
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 30/09/2025
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 05/09/2025
Asset: 1,100,007.00	Asset - Locn.: IR071 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 25/12/2025
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 30/09/2025
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 05/09/2025
Asset: 1,100,008.00	Asset - Locn.: IR072 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 25/12/2025
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 30/09/2025

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,100,008.00	Asset - Locn.: IR072 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,100,009.00	Asset - Locn.: IR073 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,100,010.00	Asset - Locn.: IR074 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,100,011.00	Asset - Locn.: IR075 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,100,012.00	Asset - Locn.: IR076 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								
Asset: 1,100,013.00	Asset - Locn.: IR077 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch				Route: A45 Full				Date: 25/12/2025
No actionable defects found								
Batch: 82865654 - Inspection Batch				Route: A45 Full				Date: 30/09/2025
No actionable defects found								
Batch: 82839301 - Inspection Batch				Route: A45 Full				Date: 05/09/2025
No actionable defects found								

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1,100,014.00	Asset - Locn.: IR078 - WELLINGBOROUGH BYPASS			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 25/12/2025
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 30/09/2025
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 05/09/2025
Asset: 1,100,015.00	Asset - Locn.: IR079 - WELLINGBOROUGH BYPASS E/BOUND			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 25/12/2025
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 30/09/2025
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 05/09/2025
Asset: 1,100,016.00	Asset - Locn.: IR080 - WELLINGBOROUGH BYPASS E/BOUND			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 25/12/2025
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 30/09/2025
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 05/09/2025
Asset: 1,100,017.00	Asset - Locn.: IR081 - WELLINGBOROUGH BYPASS E/BOUND			Feature Type: Lighting Column			Area: R23WA 13 NS	
Batch: 82921439 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 25/12/2025
Batch: 82865654 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 30/09/2025
Batch: 82839301 - Inspection Batch	No actionable defects found			Route: A45 Full				Date: 05/09/2025

Customer Services

Enquiry No.: 37802161

Logged by: [REDACTED]

on: 12/12/2025 15:29

Service: Drainage

Subject: DR: Flooding

Classification: Customer Enquiry

Enquiry Ref: 23627193

Desc.: "A45 both directi9ns right between raunds and wellingborough the drainage on the a45 is appall8ng everytime it rains hige amount of stabdbg water even in newly resurfsced area especially near central reservation . causing aquaplaning. plase can the whole of a45 be reviewed in this location its very dangerous amiubt of surface water."

Location: Higham Road, Little Irchester, Irchester, North Northamptonshire, England, NN8 2DH, United Kingdom

Contact:

Plot Number: 660,006.00

Feature Id - Location:

Feature Type: Road Stud

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: 2800A45/166 - A45 / NB / END OF WELLINGBOROUGH ENTR		Feature Type: Dual 2-Lane or one-way 2-Lane		Area: R23WA 13 NS	
41711775	Review of third party design submissions	A45 Stanton cross	Scheme	Variation Committed	16/07/2019	31/03/2020	Est. 092356/62000511
43101759	IN: Cond of Hway - Pothole - LARGE POTHOLE (Enquiry 11710439)	A45 WB APPROX MP 176/2	30 Minutes	Job Closed	20/08/2020	20/08/2020	Est. 092323/61022701
43372144	IN: Cond of Hway - Pothole - From MOP - Complaint about number of potholes on A45 - Please assess this section in both directions and raise any necessary defects. (Enquiry 11726445)	A45 EB and WB between Wilby Way and Knuston	* Priority - Change Me	No code allocated	23/01/2023		
43512972	Please resurface large depression across 2 lanes for 70mtr at 100mm depth and replace all relevant road markings (Pavement Defect)	A45 e/b 175/7 to 175/6 in lane one	Monitor Only	Job Created	11/08/2023		
71039291	Route 23: August 2016: 4.1.2: Initial grass cutting and litter clearance (verge)		28 days	Job Closed	07/09/2016	10/10/2016	Est. 092323/61000796
71039577	Route 23: August 16: 4.1.3: Initial grass cutting and litter clearance (central reserve)		28 days	Job Closed	08/09/2016	10/10/2016	Est. 092323/61000813
71156967	IN: Road Traffic Collision - SINGLE VEHICLE RTC (Enquiry 11009056)	A45 EB WILBY WAY TO LITTLE IRCHESTER	20 Minutes	Job Closed	24/08/2017	24/08/2017	Est. 092323/61005834
	Asset: 83,000.00	Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
60106448	4.4.2 - Marker posts - Clean all traffic post faces and reference numbers / Route 23: A45 / MRP 2025-26 (East Midlands - Marker Post Cleaning)		1 Month	Job Closed	19/03/2025	01/08/2025	Act. 092329/62700458
	Asset: 83,001.00	Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
60106449	4.4.2 - Marker posts - Clean all traffic post faces and reference numbers / Route 23: A45 / MRP 2025-26 (East Midlands - Marker Post Cleaning)		1 Month	Job Closed	19/03/2025	01/08/2025	Act. 092329/62700458
	Asset: 83,003.00	Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
60106450	4.4.2 - Marker posts - Clean all traffic post faces and reference numbers / Route 23: A45 / MRP 2025-26 (East Midlands - Marker Post Cleaning)		1 Month	Job Closed	19/03/2025	01/08/2025	Act. 092329/62700458

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 83,004.00	Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
60106451	4.4.2 - Marker posts - Clean all traffic post faces and reference numbers / Route 23: A45 / MRP 2025-26 (East Midlands - Marker Post Cleaning)		1 Month	Job Closed	19/03/2025	01/08/2025	Act. 092329/62700458
	Asset: 83,005.00	Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
41751998	Route 23 (A45) 4.3.1: 1200: Traffic Signs: Clean all reference numbers - marker posts / 2020 - 21 (Provide/Supply evidence of completed works in line with CRMDP) (Cyclic Maintenance of Marker Posts)		24 Hours	Job Closed	26/03/2020	12/06/2020	Est. 092323/61021226
	Asset: 83,006.00	Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
60106452	4.4.2 - Marker posts - Clean all traffic post faces and reference numbers / Route 23: A45 / MRP 2025-26 (East Midlands - Marker Post Cleaning)		1 Month	Job Closed	19/03/2025	01/08/2025	Act. 092329/62700458
	Asset: 83,007.00	Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
60106453	4.4.2 - Marker posts - Clean all traffic post faces and reference numbers / Route 23: A45 / MRP 2025-26 (East Midlands - Marker Post Cleaning)		1 Month	Job Closed	19/03/2025	01/08/2025	Act. 092329/62700458
	Asset: 83,008.00	Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
60106454	4.4.2 - Marker posts - Clean all traffic post faces and reference numbers / Route 23: A45 / MRP 2025-26 (East Midlands - Marker Post Cleaning)		1 Month	Job Closed	19/03/2025	01/08/2025	Act. 092329/62700458
	Asset: 83,009.00	Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
60106455	4.4.2 - Marker posts - Clean all traffic post faces and reference numbers / Route 23: A45 / MRP 2025-26 (East Midlands - Marker Post Cleaning)		1 Month	Job Closed	19/03/2025	01/08/2025	Act. 092329/62700458

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 83,010.00		Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
60106456	4.4.2 - Marker posts - Clean all traffic post faces and reference numbers / Route 23: A45 / MRP 2025-26 (East Midlands - Marker Post Cleaning)		1 Month	Job Closed	19/03/2025	21/08/2025	Act. 092329/62700458
Asset: 83,011.00		Asset - Locn.:		Feature Type: Reference Marker		Area: R23WA 13 NS	
60106457	4.4.2 - Marker posts - Clean all traffic post faces and reference numbers / Route 23: A45 / MRP 2025-26 (East Midlands - Marker Post Cleaning)		1 Month	Job Closed	19/03/2025	01/08/2025	Act. 092329/62700458
Asset: 120,000.00		Asset - Locn.:		Feature Type: Combined Surface and sub-Surf		Area: R23WA 13 NS	
60210970	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (1 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Contractor Rejected	30/03/2025	28/06/2025	Est. 092329/62700649
60211745	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (2 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Contractor Rejected	30/03/2025	23/08/2025	Est. 092329/62700650
60212520	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (3 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Job Committed	30/03/2025	21/03/2026	Est. 092329/62700651
Asset: 120,001.00		Asset - Locn.:		Feature Type: Combined Surface and sub-Surf		Area: R23WA 13 NS	
60210971	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (1 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Contractor Rejected	30/03/2025	28/06/2025	Est. 092329/62700649
60211746	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (2 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Contractor Rejected	30/03/2025	23/08/2025	Est. 092329/62700650

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order	
Asset: 120,001.00		Asset - Locn.: .	Feature Type: Combined Surface and sub-Surf					Area: R23WA 13 NS
60212521	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (3 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Job Committed	30/03/2025	21/03/2026	Est. 092329/62700651	
Asset: 120,002.00		Asset - Locn.:	Feature Type: Combined Surface and sub-Surf					Area: R23WA 13 NS
60210972	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (1 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Contractor Rejected	30/03/2025	28/06/2025	Est. 092329/62700649	
60211747	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (2 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Contractor Rejected	30/03/2025	23/08/2025	Est. 092329/62700650	
60212522	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (3 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Job Committed	30/03/2025	21/03/2026	Est. 092329/62700651	
Asset: 120,003.00		Asset - Locn.:	Feature Type: Combined Surface and sub-Surf					Area: R23WA 13 OS
60210973	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (1 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Substantiation Passed	30/03/2025	19/09/2025	Act. 092329/62700649	
60211748	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (2 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Substantiation Passed	30/03/2025	28/10/2025	Act. 092329/62700650	
60212523	4.3.11.2a - Filter Drains - Weed spray along Filter Drain and Combined carrier and Filter drain / Route 23: A45 / MRP 2025-26 (3 of 3) (East Midlands - Weed Spray of Filter Drains (<3m))		1 Month	Job Committed	30/03/2025	21/03/2026	Est. 092329/62700651	

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 150,000.00		Asset - Locn.: .		Feature Type: Catch pit		Area: R23WA 13 NS	
41776389	Route 23 (A45) 4.2.4: 500: Catch Pits: Clean & empty catch pits / 2020 - 21 (Provide/Supply evidence of completed works in line with CRMDP) (Cyclic Cleansing of Catchpits)		24 Hours	Post Compl Inspection Failed	02/04/2020	31/03/2021	Est. 092323/61021346
43179917	4.2.4: 500: Catch Pits: Clean & empty catch pits / 2021 - 22 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Catchpits)		28 days	Job Cancelled	25/02/2021	15/06/2021	Est. 092323/61026043
43401304	4.3.4 - Catch pit: Clear weed / vegetation growth around frames, clear, empty silt and debris from Catch Pits / Route 23: A45 / MRP 2023/24 (Area 7 - Cyclic Cleansing of Catchpits)		1 Month	Substantiation Passed	16/02/2023	05/08/2023	Est. 092329/62341318
Asset: 150,001.00		Asset - Locn.: .		Feature Type: Catch pit		Area: R23WA 13 OS	
41776390	Route 23 (A45) 4.2.4: 500: Catch Pits: Clean & empty catch pits / 2020 - 21 (Provide/Supply evidence of completed works in line with CRMDP) (Cyclic Cleansing of Catchpits)		24 Hours	Post Compl Inspection Failed	02/04/2020	31/03/2021	Est. 092323/61021346
43179918	4.2.4: 500: Catch Pits: Clean & empty catch pits / 2021 - 22 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Catchpits)		28 days	Substantiation Passed	25/02/2021	15/02/2022	Est. 092323/61026044
43401765	4.3.4 - Catch pit: Clear weed / vegetation growth around frames, clear, empty silt and debris from Catch Pits / Route 23: A45 / MRP 2023/24 (Area 7 - Cyclic Cleansing of Catchpits)		1 Month	Substantiation Passed	16/02/2023	09/08/2023	Est. 092329/62341342

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 150,002.00		Asset - Locn.: This asset no longer at site. .		Feature Type: Catch pit		Area: R23WA 13 NS	
41776391	Route 23 (A45) 4.2.4: 500: Catch Pits: Clean & empty catch pits / 2020 - 21 (Provide/Supply evidence of completed works in line with CRMDP) (Cyclic Cleansing of Catchpits)		24 Hours	Post Compl Inspection Failed	02/04/2020	31/03/2021	Est. 092323/61021346
43401305	4.3.4 - Catch pit: Clear weed / vegetation growth around frames, clear, empty silt and debris from Catch Pits / Route 23: A45 / MRP 2023/24 (Area 7 - Cyclic Cleansing of Catchpits)		1 Month	Substantiation Passed	16/02/2023	05/08/2023	Est. 092329/62341318
Asset: 150,003.00		Asset - Locn.: .		Feature Type: Catch pit		Area: R23WA 13 OS	
41776392	Route 23 (A45) 4.2.4: 500: Catch Pits: Clean & empty catch pits / 2020 - 21 (Provide/Supply evidence of completed works in line with CRMDP) (Cyclic Cleansing of Catchpits)		24 Hours	Post Compl Inspection Failed	02/04/2020	31/03/2021	Est. 092323/61021346
60072317	4.3.4 - Catch pit - Clear weed / vegetation growth around frames, clear, empty silt and debris from Catch Pits / Route 23: A45 / MRP 2025-26 (East Midlands - Catchpit Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Est. 092329/62700400
Asset: 150,004.00		Asset - Locn.: .		Feature Type: Catch pit		Area: R23WA 13 NS	
41776393	Route 23 (A45) 4.2.4: 500: Catch Pits: Clean & empty catch pits / 2020 - 21 (Provide/Supply evidence of completed works in line with CRMDP) (Cyclic Cleansing of Catchpits)		24 Hours	Post Compl Inspection Failed	02/04/2020	31/03/2021	Est. 092323/61021346
43179921	4.2.4: 500: Catch Pits: Clean & empty catch pits / 2021 - 22 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Catchpits)		28 days	Job Cancelled	25/02/2021	15/06/2021	Est. 092323/61026043

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 150,004.00		Asset - Locn.: .		Feature Type: Catch pit		Area: R23WA 13 NS	
43401306	4.3.4 - Catch pit: Clear weed / vegetation growth around frames, clear, empty silt and debris from Catch Pits / Route 23: A45 / MRP 2023/24 (Area 7 - Cyclic Cleansing of Catchpits)		1 Month	Substantiation Passed	16/02/2023	05/08/2023	Est. 092329/62341318
Asset: 150,005.00		Asset - Locn.: .		Feature Type: Catch pit		Area: R23WA 13 NS	
41776394	Route 23 (A45) 4.2.4: 500: Catch Pits: Clean & empty catch pits / 2020 - 21 (Provide/Supply evidence of completed works in line with CRMDP) (Cyclic Cleansing of Catchpits)		24 Hours	Post Compl Inspection Failed	02/04/2020	31/03/2021	Est. 092323/61021346
43179922	4.2.4: 500: Catch Pits: Clean & empty catch pits / 2021 - 22 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Catchpits)		28 days	Job Cancelled	25/02/2021	11/02/2022	Est. 092323/61026043
60072318	4.3.4 - Catch pit - Clear weed / vegetation growth around frames, clear, empty silt and debris from Catch Pits / Route 23: A45 / MRP 2025-26 (East Midlands - Catchpit Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700400
Asset: 150,006.00		Asset - Locn.: .		Feature Type: Catch pit		Area: R23WA 13 OS	
41776395	Route 23 (A45) 4.2.4: 500: Catch Pits: Clean & empty catch pits / 2020 - 21 (Provide/Supply evidence of completed works in line with CRMDP) (Cyclic Cleansing of Catchpits)		24 Hours	Post Compl Inspection Failed	02/04/2020	31/03/2021	Est. 092323/61021346
43179923	4.2.4: 500: Catch Pits: Clean & empty catch pits / 2021 - 22 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Catchpits)		28 days	Substantiation Passed	25/02/2021	15/02/2022	Est. 092323/61026044

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 150,006.00		Asset - Locn.: .		Feature Type: Catch pit		Area: R23WA 13 OS	
43401767	4.3.4 - Catch pit: Clear weed / vegetation growth around frames, clear, empty silt and debris from Catch Pits / Route 23: A45 / MRP 2023/24 (Area 7 - Cyclic Cleansing of Catchpits)		1 Month	Substantiation Passed	16/02/2023	09/08/2023	Est. 092329/62341342
60072319	4.3.4 - Catch pit - Clear weed / vegetation growth around frames, clear, empty silt and debris from Catch Pits / Route 23: A45 / MRP 2025-26 (East Midlands - Catchpit Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Est. 092329/62700400
Asset: 260,040.00		Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 OS	
60061844	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
Asset: 260,054.00		Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 OS	
60061845	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
Asset: 260,068.00		Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
60061846	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
Asset: 260,070.00		Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
43388237	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	06/02/2023	05/08/2023	Est. 092329/62340588
60061847	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,071.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061848	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,072.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061849	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,073.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061850	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,074.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061851	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,075.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
43388238	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Job Cancelled	06/02/2023	05/08/2023	Est. 092329/62340588
	Asset: 260,077.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061852	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,077.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061853	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,078.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
43388239	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	06/02/2023	05/08/2023	Est. 092329/62340588
60061854	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,079.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061855	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,080.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
43171840	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Post Compl Inspection Failed	25/02/2021	15/02/2022	Est. 092323/61026074
60061856	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Unable to Complete	16/03/2025	27/08/2025	Est. 092329/62700251
	Asset: 260,081.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061857	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,083.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061858	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,084.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
43171844	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Post Compl Inspection Failed	25/02/2021	15/02/2022	Est. 092323/61026074
43389480	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Job Cancelled	07/02/2023	09/08/2023	Est. 092329/62340613
60061859	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Substantiation Passed	16/03/2025	27/08/2025	Est. 092329/62700251
	Asset: 260,085.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061860	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,086.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
43388240	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	06/02/2023	05/08/2023	Est. 092329/62340588
60061861	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,087.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061862	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,088.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
43171848	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Post Compl Inspection Failed	25/02/2021	15/02/2022	Est. 092323/61026074
60061863	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Unable to Complete	16/03/2025	27/08/2025	Est. 092329/62700251
	Asset: 260,089.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
43171849	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Substantiation Passed	25/02/2021	11/02/2022	Est. 092323/61026073
43388241	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Job Cancelled	06/02/2023	05/08/2023	Est. 092329/62340588
60061864	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,090.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061865	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,091.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061866	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,092.00	Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
60061867	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,093.00	Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
43388243	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	06/02/2023	05/08/2023	Est. 092329/62340588
60061868	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,094.00	Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
43388244	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Job Cancelled	06/02/2023	05/08/2023	Est. 092329/62340588
60061869	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,095.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
43171855	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Substantiation Passed	25/02/2021	15/02/2022	Est. 092323/61026074
43389486	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	07/02/2023	09/08/2023	Est. 092329/62340613

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,095.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061870	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Est. 092329/62700251
	Asset: 260,096.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
43389487	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	07/02/2023	09/08/2023	Est. 092329/62340613
60061871	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Unable to Complete	16/03/2025	27/08/2025	Est. 092329/62700251
	Asset: 260,097.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061872	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,098.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061873	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,099.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
43389490	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	07/02/2023	09/08/2023	Est. 092329/62340613
60061874	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,100.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
43171860	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Substantiation Passed	25/02/2021	15/02/2022	Est. 092323/61026074
43389491	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	07/02/2023	09/08/2023	Est. 092329/62340613
60061875	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Est. 092329/62700251
	Asset: 260,101.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061876	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,102.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061877	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,103.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061878	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,104.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061879	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,105.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061880	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,106.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061881	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,107.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061882	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,108.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061883	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,109.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
43389500	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	07/02/2023	09/08/2023	Est. 092329/62340613
	Asset: 260,110.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
43388245	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Job Cancelled	06/02/2023	05/08/2023	Est. 092329/62340588

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,110.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
60061885	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,111.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061886	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,112.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061887	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,113.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061888	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,114.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061889	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,115.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
43171875	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Substantiation Passed	25/02/2021	11/02/2022	Est. 092323/61026073
43388246	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Job Cancelled	06/02/2023	05/08/2023	Est. 092329/62340588

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,115.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
60061890	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,116.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
43171876	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Substantiation Passed	25/02/2021	11/02/2022	Est. 092323/61026073
43388247	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	06/02/2023	05/08/2023	Est. 092329/62340588
	Asset: 260,117.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061891	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,118.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061892	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,119.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061893	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,120.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061894	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,121.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
43171881	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Substantiation Passed	25/02/2021	15/02/2022	Est. 092323/61026074
43389509	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	07/02/2023	09/08/2023	Est. 092329/62340613
60061895	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Unable to Complete	16/03/2025	27/08/2025	Est. 092329/62700251
	Asset: 260,122.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061896	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,123.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061897	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,124.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061898	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,125.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061899	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,126.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
43389514	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	07/02/2023	09/08/2023	Est. 092329/62340613
60061900	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,127.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061901	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,128.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061902	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,129.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 OS	
60061903	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	Job Closed	16/03/2025	27/08/2025	Act. 092329/62700251
	Asset: 260,130.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
60061904	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,131.00	Asset - Locn.:		Feature Type: Gully		Area: R23WA 13 NS	
60061905	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,132.00	Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
60061906	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,133.00	Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
43388251	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	06/02/2023	05/08/2023	Est. 092329/62340588
60061907	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,134.00	Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
43171894	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Substantiation Passed	25/02/2021	11/02/2022	Est. 092323/61026073
43388252	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Substantiation Passed	06/02/2023	05/08/2023	Est. 092329/62340588
60061908	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,135.00	Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
60061909	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,136.00	Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
43171896	4.2.1: 500: Gullies: Gullies - emptying & clear covers / 2021-2022 / Route 23 (A45) (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Cleansing of Gullies)		28 days	Substantiation Passed	25/02/2021	11/02/2022	Est. 092323/61026073
43388254	4.3.1.1 - Gullies: Gully Emptying, including clearing aprons, covers and obstructions / Route 23:M69 Junc 1 - M1 Junc 21 / MRP 2023/24 (Cyclic Cleansing of Gullies)		1 Month - Commit	Job Cancelled	06/02/2023	05/08/2023	Est. 092329/62340588
60061910	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 260,137.00	Asset - Locn.: .		Feature Type: Gully		Area: R23WA 13 NS	
60061911	4.3.1.1 - Gullies - Gully Emptying, including clearing aprons, covers and obstructions / Route 23: A45 / MRP 2025-26 (East Midlands - Gully Cleanse)		1 Month	For Scheduling	16/03/2025	26/02/2026	Est. 092329/62700251
	Asset: 320,001.00	Asset - Locn.:		Feature Type: Manhole		Area: R23WA 13 NS	
43497325	4.3.8: - Manholes: Clear manholes by removing all material that could impair operation (overgrown vegetation / weed, silt, debris / rubbish) / Route 23: A45 / MRP 2023/24 (Area 7 - Cyclic Cleansing of Manholes)		1 Month	Substantiation Passed	01/04/2023	05/08/2023	Est. 092329/62349847
	Asset: 320,003.00	Asset - Locn.: .		Feature Type: Manhole		Area: R23WA 13 NS	
43497327	4.3.8: - Manholes: Clear manholes by removing all material that could impair operation (overgrown vegetation / weed, silt, debris / rubbish) / Route 23: A45 / MRP 2023/24 (Area 7 - Cyclic Cleansing of Manholes)		1 Month	Substantiation Passed	01/04/2023	05/08/2023	Est. 092329/62349847

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 320,007.00	Asset - Locn.:		Feature Type: Manhole		Area: R23WA 13 NS	
43497330	4.3.8: - Manholes: Clear manholes by removing all material that could impair operation (overgrown vegetation / weed, silt, debris / rubbish) / Route 23: A45 / MRP 2023/24 (Area 7 - Cyclic Cleansing of Manholes)		1 Month	Job Cancelled	01/04/2023	01/10/2023	Est. 092329/62349847
	Asset: 320,008.00	Asset - Locn.:		Feature Type: Manhole		Area: R23WA 13 NS	
43497331	4.3.8: - Manholes: Clear manholes by removing all material that could impair operation (overgrown vegetation / weed, silt, debris / rubbish) / Route 23: A45 / MRP 2023/24 (Area 7 - Cyclic Cleansing of Manholes)		1 Month	Job Cancelled	01/04/2023	01/10/2023	Est. 092329/62349847
	Asset: 680,000.00	Asset - Locn.:		Feature Type: Sign Face		Area: R23WA 13 NS	
60085344	4.4.1.1 - Traffic Signs - Clean all traffic sign faces and reference numbers areas less than 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning <5m2)		1 Month	Job Closed	18/03/2025	01/08/2025	Act. 092329/62700422
60098112	4.4.1.2 - Traffic Signs - Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning >=5m2)		1 Month	Job Cancelled	19/03/2025	01/04/2026	Est. 092329/62700445
	Asset: 680,001.00	Asset - Locn.:		Feature Type: Sign Face		Area: R23WA 13 NS	
60085345	4.4.1.1 - Traffic Signs - Clean all traffic sign faces and reference numbers areas less than 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning <5m2)		1 Month	Job Closed	18/03/2025	01/08/2025	Act. 092329/62700422
60098113	4.4.1.2 - Traffic Signs - Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning >=5m2)		1 Month	Job Cancelled	19/03/2025	01/04/2026	Est. 092329/62700445

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 680,002.00	Asset - Locn.:		Feature Type: Sign Face		Area: R23WA 13 NS	
60085346	4.4.1.1 - Traffic Signs - Clean all traffic sign faces and reference numbers areas less than 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning <5m2)		1 Month	Job Closed	18/03/2025	01/08/2025	Act. 092329/62700422
60098114	4.4.1.2 - Traffic Signs - Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning >=5m2)		1 Month	Job Cancelled	19/03/2025	01/04/2026	Est. 092329/62700445
	Asset: 680,003.00	Asset - Locn.:		Feature Type: Sign Face		Area: R23WA 13 NS	
41746359	Route 23 (A45) 4.3.1: 1200: Traffic Signs: Clean all traffic sign faces / 2020 - 21 (Provide/Supply evidence of completed works in line with CRMDP) (Cyclic Maintenance of Non-Illuminated Signs)		24 Hours	Job Closed	25/03/2020	12/06/2020	Est. 092323/61021177
60085347	4.4.1.1 - Traffic Signs - Clean all traffic sign faces and reference numbers areas less than 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning <5m2)		1 Month	Job Closed	18/03/2025	02/08/2025	Est. 092329/62700422
60098115	4.4.1.2 - Traffic Signs - Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning >=5m2)		1 Month	Job Cancelled	19/03/2025	01/04/2026	Est. 092329/62700445
	Asset: 680,004.00	Asset - Locn.:		Feature Type: Sign Face		Area: R23WA 13 NS	
60085348	4.4.1.1 - Traffic Signs - Clean all traffic sign faces and reference numbers areas less than 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning <5m2)		1 Month	Job Closed	18/03/2025	01/08/2025	Act. 092329/62700422
60098116	4.4.1.2 - Traffic Signs - Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning >=5m2)		1 Month	Job Cancelled	19/03/2025	01/04/2026	Est. 092329/62700445

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 680,005.00		Asset - Locn.:		Feature Type: Sign Face		Area: R23WA 13 NS	
60085349	4.4.1.1 - Traffic Signs - Clean all traffic sign faces and reference numbers areas less than 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning <5m2)		1 Month	Job Closed	18/03/2025	01/08/2025	Act. 092329/62700422
60098117	4.4.1.2 - Traffic Signs - Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning >=5m2)		1 Month	Job Cancelled	19/03/2025	01/04/2026	Est. 092329/62700445
Asset: 680,006.00		Asset - Locn.:		Feature Type: Sign Face		Area: R23WA 13 NS	
60085350	4.4.1.1 - Traffic Signs - Clean all traffic sign faces and reference numbers areas less than 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning <5m2)		1 Month	Job Closed	18/03/2025	21/08/2025	Act. 092329/62700422
60098118	4.4.1.2 - Traffic Signs - Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 / Route 23: A45 / MRP 2025-26 (East Midlands - Sign Cleaning >=5m2)		1 Month	Job Cancelled	19/03/2025	01/04/2026	Est. 092329/62700445
Asset: 780,000.00		Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60038430	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	01/08/2025	Act. 092329/62700261
Asset: 780,001.00		Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60038431	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	01/08/2025	Act. 092329/62700261

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,002.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041558	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,003.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 OS	
43156845	4.1.4: 400: Vehicle restraint system, and all barrier systems (excluding concrete barriers): Check all safety barriers and re-tension Tension Corrugated Beam (TCB) safety barriers / Route 23 (A45) / 2021 - 2022 (Provide/Supply evidence of completed works in line with ADAMR/CRMDP) (Area 7 - Cyclic Safety Barrier Checks)		28 days	Job Cancelled	22/02/2021	10/02/2022	Est. 092323/61025978
60038432	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	26/08/2025	Act. 092329/62700261
	Asset: 780,004.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60038433	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	01/08/2025	Act. 092329/62700261
	Asset: 780,005.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 OS	
60038434	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	26/08/2025	Act. 092329/62700261

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,006.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 OS	
60038435	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	26/08/2025	Act. 092329/62700261
	Asset: 780,007.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041559	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,008.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60038436	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	01/08/2025	Act. 092329/62700261
	Asset: 780,009.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60038437	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	01/08/2025	Act. 092329/62700261
	Asset: 780,010.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60038438	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	01/08/2025	Act. 092329/62700261

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,011.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041560	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,012.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041561	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,013.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041562	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,014.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041563	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,015.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041564	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,016.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041565	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,017.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60038439	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	01/08/2025	Act. 092329/62700261

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,018.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041566	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,019.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041567	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,020.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041568	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,021.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041569	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,022.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041570	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,023.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041571	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,024.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041572	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,025.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041573	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,026.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041574	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,027.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041575	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,028.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041576	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 780,029.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041577	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,030.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 13 NS	
60041578	4.2.1, 4.2.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System, Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. / Route 23; A45 / MRP 2025-26 (East Midland - Tension and Check Safety Barrier)		1 Month	Job Closed	14/03/2025	01/08/2025	Act. 092329/62700266
	Asset: 788,001.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: R23WA 14 OS	
60038440	4.2.1 - Road restraint system, and all barrier systems (excluding concrete barriers) - Check all Road Restraint System / Route 23; A45 / MRP 2025-26 (East Midlands - Untensioned Safety Barrier Checks)		1 Month	Job Closed	13/03/2025	26/08/2025	Act. 092329/62700261
	Asset: 1,030,002.00	Asset - Locn.: IR073 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: R23WA 13 NS	
43108819	Area 7 Door Off (Area 7 Door Off)		SL: Light Out 6 Months	Job Closed	20/10/2020		
	Asset: 1,030,015.00	Asset - Locn.: WE004/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: R23WA 13 OS	
41735270	SL: Lighting Out - 6 Month (SL: Lighting Out - 6 Month)		SL: Light Out 6 Months	Job Closed	06/03/2020		
43121053	SL: Lighting Out - 6 Month (SL: Lighting Out - 6 Month)		* Priority - Change Me	Job Closed	21/01/2021		
43121054	SL: Lighting Out - 6 Month (SL: Lighting Out - 6 Month)		SL: Light Out 6 Months	Job Closed	21/01/2021		
	Asset: 1,030,017.00	Asset - Locn.: WE005/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: R23WA 13 OS	
43223494	Area 7 Light on During the day (Area 7 Light on During the day)		6 months	Job Cancelled	08/04/2021	27/07/2021	Est. 092325/61428983
43237540	Area 7 Light on During the day (Area 7 Light on During the day)		6 months	Job Cancelled	06/12/2021		
71061984	SL: Lamp on during day	South bound in the centre reservation	6 months	Job Closed	04/10/2016	06/04/2017	Est. 092325/61402839
	Asset: 1,030,020.00	Asset - Locn.: WE007/A - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: R23WA 13 OS	
41735271	SL: Lighting Out - 6 Month (SL: Lighting Out - 6 Month)		SL: Light Out 6 Months	Job Closed	06/03/2020		
43121055	SL: Lighting Out - 6 Month (SL: Lighting Out - 6 Month)		SL: Light Out 6 Months	Job Closed	21/01/2021		
43123907	SL: Not on 6 months (Area 7 Not on 6 Months)		SL: Light Out 6 Months	Job Closed	25/01/2021		

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,030,020.00	Asset - Locn.: WE007/A - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: R23WA 13 OS	
43226464	Area 7 Not on 6 Months (Area 7 Not on 6 Months)		6 months	Job Cancelled	13/05/2021	17/11/2021	Est. 092325/61429756
43235496	Area 7 Not on 6 Months (Area 7 Not on 6 Months) Investigate fault and repair using new components as required		6 months	Job Cancelled	17/11/2021		
43361711	Area 7 Light on During the day INVESTIGATE FAULT		6 months	Job Cancelled	16/08/2022		
71196085	SL: Not on 6 months (SL: Not on 6 months)		SL: Light Out 6 Months	Job Closed	16/10/2018		
	Asset: 1,030,021.00	Asset - Locn.: WE007/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: R23WA 13 OS	
43123769	SL: Not on 6 months (Area 7 Not on 6 Months)		SL: Light Out 6 Months	Job Closed	25/01/2021		
71200180	SL: Not on 6 months (SL: Not on 6 months)		SL: Light Out 6 Months	Job Closed	20/12/2018		
	Asset: 1,030,024.00	Asset - Locn.: WE009/A - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: R23WA 13 OS	
43235495	Area 7 Not on 6 Months (Area 7 Not on 6 Months) Investigate fault and repair using new components as required		6 months	Job Cancelled	17/11/2021		
	Asset: 1,030,025.00	Asset - Locn.: WE009/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: R23WA 13 OS	
43235494	Area 7 Not on 6 Months (Area 7 Not on 6 Months) Investigate fault and repair using new components as required		6 months	Job Cancelled	17/11/2021		
	Asset: 1,030,026.00	Asset - Locn.: WE010/A - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: R23WA 13 OS	
43108820	Area 7 Door Off (Area 7 Door Off)		SL: Light Out 6 Months	Job Closed	20/10/2020		
	Asset: 1,030,041.00	Asset - Locn.: WE002/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: R23WA 13 OS	
43237539	Area 7 Light on During the day (Area 7 Light on During the day)		6 months	Job Cancelled	06/12/2021		
	Asset: 1,030,042.00	Asset - Locn.: WE003/A - Turnmills Eastbound Slip Road		Feature Type: Lighting Unit		Area: R23WA 13 OS	
43353394	Area 7 Light on During the day (Area 7 Light on During the day)		6 months	Job Cancelled	14/04/2022		
	Asset: 1,030,044.00	Asset - Locn.: WE008/A - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43418566	Area 7 Not on 6 Months (Area 7 Not on 6 Months)		6 months	Job Closed	28/02/2023		
43530532	Lighting Out (Lighting Out)		28 days	Work Suspended HE	17/11/2024		
	Asset: 1,030,045.00	Asset - Locn.: WE008/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43418567	Area 7 Not on 6 Months (Area 7 Not on 6 Months)		6 months	Job Closed	28/02/2023		

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,030,045.00	Asset - Locn.: WE008/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43520102	Area 7 Not on 14 Days (Area 7 Not on 14 Days) Investigate fault and repair using new components as required. Amey to repair or request a variation if required. Renew and bring back into maintenance.		14 days	Job Cancelled	07/02/2024		
43530534	Lighting Out (Lighting Out)		28 days	Work Suspended HE	17/11/2024		
	Asset: 1,030,048.00	Asset - Locn.: WE011/A - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43364463	Area 7 Not on 6 Months (Area 7 Not on 6 Months)		6 months	Job Cancelled	06/10/2022		
43369950	Area 7 Not on 6 Months (Area 7 Not on 6 Months)		6 months	Job Closed	13/12/2022		
43522548	Area 7 Block Outage (Area 7 Block Outage)Investigate fault and repair using new components as required. Amey to repair or request a variation if required. Renew and bring back in to maintenance		7 days	Job Cancelled	19/03/2024		
	Asset: 1,030,049.00	Asset - Locn.: WE011/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43364462	Area 7 Not on 6 Months (Area 7 Not on 6 Months)		6 months	Job Cancelled	06/10/2022		
43369949	Area 7 Not on 6 Months (Area 7 Not on 6 Months)		6 months	Job Closed	13/12/2022		
	Asset: 1,030,050.00	Asset - Locn.: WE012/A - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43530536	Lighting Out (Lighting Out)		28 days	Work Suspended HE	17/11/2024		
	Asset: 1,030,051.00	Asset - Locn.: WE012/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43514740	Area 7 Not on 6 Months (Area 7 Not on 6 Months)		6 months	Job Closed	10/10/2023		
43530535	Lighting Out (Lighting Out)		28 days	Work Suspended HE	17/11/2024		
	Asset: 1,030,052.00	Asset - Locn.: WE013/A - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43530560	Lighting Out (Lighting Out)		28 days	Work Suspended HE	17/11/2024		
	Asset: 1,030,053.00	Asset - Locn.: WE013/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43530561	Lighting Out (Lighting Out)		28 days	Work Suspended HE	17/11/2024		
	Asset: 1,030,054.00	Asset - Locn.: WE014/A - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43530559	Lighting Out (Lighting Out)		28 days	Work Suspended HE	17/11/2024		
	Asset: 1,030,055.00	Asset - Locn.: WE014/B - WELLINGBOROUGH BYPASS		Feature Type: Lighting Unit		Area: No code allocated	
43530558	Lighting Out (Lighting Out)		28 days	Work Suspended HE	17/11/2024		

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,050,000.00	Asset - Locn.: IR071 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
43331668	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured / 2022 / Route 23 (A45) (Provide evidence of completed works in line with ADAMR) (Area 7 - Cyclic Illumination Cuts)		6 months	Job Closed	30/03/2022	10/08/2022	Est. 092329/62340048
71500748	Bulk C&C Street Lighting		28 days	Job Cancelled	31/08/2018		
	Asset: 1,050,001.00	Asset - Locn.: IR072 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
71500749	Bulk C&C Street Lighting		28 days	Job Cancelled	31/08/2018		
	Asset: 1,050,002.00	Asset - Locn.: IR073 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
71500750	Bulk C&C Street Lighting		28 days	Job Cancelled	31/08/2018		
	Asset: 1,050,003.00	Asset - Locn.: IR074 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
43331671	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured / 2022 / Route 23 (A45) (Provide evidence of completed works in line with ADAMR) (Area 7 - Cyclic Illumination Cuts)		6 months	Job Closed	30/03/2022	10/08/2022	Est. 092329/62340048
71500751	Bulk C&C Street Lighting		28 days	Job Cancelled	31/08/2018		
	Asset: 1,050,004.00	Asset - Locn.: IR075 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
43331672	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured / 2022 / Route 23 (A45) (Provide evidence of completed works in line with ADAMR) (Area 7 - Cyclic Illumination Cuts)		6 months	Substantiation Passed	30/03/2022	10/08/2022	Est. 092329/62340048
71500752	Bulk C&C Street Lighting		28 days	Job Cancelled	31/08/2018		
	Asset: 1,050,005.00	Asset - Locn.: IR076 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
43331673	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured / 2022 / Route 23 (A45) (Provide evidence of completed works in line with ADAMR) (Area 7 - Cyclic Illumination Cuts)		6 months	Job Closed	30/03/2022	10/08/2022	Est. 092329/62340048
71500753	Bulk C&C Street Lighting		28 days	Job Cancelled	31/08/2018		
	Asset: 1,050,006.00	Asset - Locn.: IR077 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
71500754	Bulk C&C Street Lighting		28 days	Job Cancelled	31/08/2018		
	Asset: 1,050,007.00	Asset - Locn.: IR078 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
71500755	Bulk C&C Street Lighting		28 days	Job Cancelled	31/08/2018		

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,050,008.00	Asset - Locn.: WE001 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729612	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,009.00	Asset - Locn.: WE002 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729613	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,010.00	Asset - Locn.: WE003 - Turnmills Eastbound Slip Road		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729614	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,011.00	Asset - Locn.: WE004 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729615	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,012.00	Asset - Locn.: WE005 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729616	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	31/08/2020	Est. 092323/61021131
	Asset: 1,050,013.00	Asset - Locn.: WE006 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729617	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,014.00	Asset - Locn.: WE007 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41704155			6 months	Job Closed	30/05/2019		
41729618	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,015.00	Asset - Locn.: WE008 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729619	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,016.00	Asset - Locn.: WE009 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729620	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
43361716	Area 7 Light on During the day INVESTIGATE FAULT		6 months	Job Cancelled	16/08/2022		
43361717	Area 7 Light on During the day INVESTIGATE FAULT		6 months	Job Cancelled	16/08/2022		
	Asset: 1,050,017.00	Asset - Locn.: WE010 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729621	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,018.00	Asset - Locn.: WE011 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729622	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
51100977	WE011 - lighting outage,will attempt repair. (FIX NOW Lighting DefectArea 7)		Fix Now	Job Closed	19/08/2022	19/08/2022	Est.

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,050,019.00	Asset - Locn.: WE012 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729623	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,020.00	Asset - Locn.: WE013 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729624	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,021.00	Asset - Locn.: WE014 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729625	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,050,022.00	Asset - Locn.: WE015 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 OS	
41729626	A45 Street Lighting BCC works (Bulk C&C Street Lighting)		3 Months	Allocated to Crew	15/01/2020	20/10/2020	Est. 092323/61021131
	Asset: 1,100,001.00	Asset - Locn.: WE008 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
59055240	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Illumination Cuts)		1 Month	Job Cancelled	12/02/2024	31/12/2024	Est. 092329/62350982
60015602	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031049	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electical Testing)		1 Month	Job Cancelled	28/02/2024		
60150007	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	For Scheduling	28/03/2025	26/02/2026	Est. 092329/62700547
60164644	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,002.00		Asset - Locn.: WE010 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60015603	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031050	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150008	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	For Scheduling	28/03/2025	26/02/2026	Est. 092329/62700547
60164645	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,003.00		Asset - Locn.: WE011 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60015604	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031051	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150009	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	For Scheduling	28/03/2025	26/02/2026	Est. 092329/62700547

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,003.00		Asset - Locn.: WE011 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60164646	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,004.00		Asset - Locn.: WE012 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60015605	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031052	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150010	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	For Scheduling	28/03/2025	26/02/2026	Est. 092329/62700547
60164647	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,005.00		Asset - Locn.: WE013 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60015606	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031053	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,005.00		Asset - Locn.: WE013 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60150011	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	For Scheduling	28/03/2025	26/02/2026	Est. 092329/62700547
60164648	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,006.00		Asset - Locn.: WE014 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60015607	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031054	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150012	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	For Scheduling	28/03/2025	26/02/2026	Est. 092329/62700547
60164649	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,007.00		Asset - Locn.: IR071 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
59055246	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Illumination Cuts)		1 Month	Job Cancelled	12/02/2024	31/12/2024	Est. 092329/62350982

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,007.00		Asset - Locn.: IR071 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60015608	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031055	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150013	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547
60164650	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,008.00		Asset - Locn.: IR072 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
59055247	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Illumination Cuts)		1 Month	Job Cancelled	12/02/2024	31/12/2024	Est. 092329/62350982
60015609	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031056	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,008.00		Asset - Locn.: IR072 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60150014	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547
60164651	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,009.00		Asset - Locn.: IR073 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
59055248	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Illumination Cuts)		1 Month	Job Cancelled	12/02/2024	31/12/2024	Est. 092329/62350982
60015610	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031057	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150015	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547
60164652	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,010.00		Asset - Locn.: IR074 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
59055249	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Illumination Cuts)		1 Month	Job Cancelled	12/02/2024	31/12/2024	Est. 092329/62350982
60015611	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031058	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150016	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547
60164653	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,011.00		Asset - Locn.: IR075 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
59055250	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Illumination Cuts)		1 Month	Job Cancelled	12/02/2024	31/12/2024	Est. 092329/62350982
60015612	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,011.00		Asset - Locn.: IR075 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60031059	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150017	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547
60164654	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,012.00		Asset - Locn.: IR076 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
59055251	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Illumination Cuts)		1 Month	Job Cancelled	12/02/2024	31/12/2024	Est. 092329/62350982
60015613	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031060	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150018	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,012.00		Asset - Locn.: IR076 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60164655	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,013.00		Asset - Locn.: IR077 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
59055252	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Illumination Cuts)		1 Month	Job Cancelled	12/02/2024	31/12/2024	Est. 092329/62350982
60015614	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031061	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150019	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547
60164656	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,014.00		Asset - Locn.: IR078 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
59055253	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Illumination Cuts)		1 Month	Job Cancelled	12/02/2024	31/12/2024	Est. 092329/62350982

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,014.00		Asset - Locn.: IR078 - WELLINGBOROUGH BYPASS		Feature Type: Lighting Column		Area: R23WA 13 NS	
60015615	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031062	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150020	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547
60164657	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,015.00		Asset - Locn.: IR079 - WELLINGBOROUGH BYPASS E/BOUND		Feature Type: Lighting Column		Area: R23WA 13 NS	
59055254	4.8.4.1 - Grass and vegetation: Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Illumination Cuts)		1 Month	Job Cancelled	12/02/2024	31/12/2024	Est. 092329/62350982
60015616	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031063	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,015.00		Asset - Locn.: IR079 - WELLINGBOROUGH BYPASS E/BOUND		Feature Type: Lighting Column		Area: R23WA 13 NS	
60150021	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547
60164658	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,016.00		Asset - Locn.: IR080 - WELLINGBOROUGH BYPASS E/BOUND		Feature Type: Lighting Column		Area: R23WA 13 NS	
60015617	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		
60031064	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150022	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547
60164659	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,100,017.00		Asset - Locn.: IR081 - WELLINGBOROUGH BYPASS E/BOUND		Feature Type: Lighting Column		Area: R23WA 13 NS	
60015618	4.5.10 - Lighting columns (<20m in height): Structural testing from 15 years old / Route 23: A45 / MRP 2024/25 (Area 7 - Lighting Structural Testing)		1 Month	Job Cancelled	28/02/2024		

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,100,017.00		Asset - Locn.: IR081 - WELLINGBOROUGH BYPASS E/BOUND		Feature Type: Lighting Column		Area: R23WA 13 NS	
60031065	4.5.9 - Network cabling and electrical components including feeder pillars: Electrical testing / Route 23: A45 / MRP 2024/25 (Area 7 - Network Cabling and Electrical Testing)		1 Month	Job Cancelled	28/02/2024		
60150023	4.8.4.1a - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Summer)		1 Month	Job Closed	28/03/2025	01/08/2025	Act. 092329/62700547
60164660	4.8.4.1b - Grass and vegetation - Ensure illumination/lumination from lighting is not obscured. / Route 23: A45 / MRP 2025-26 (East Midlands - Illumination Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700567
Asset: 1,666,001.00		Asset - Locn.: R23WA 13 NS		Feature Type: Splay/Swath		Area: R23WA 13 NS	
59072563	4.8.5.2 - Grass and vegetation: Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Verge Swathe)		1 Month	Job Cancelled	12/02/2024	30/03/2025	Est. 092329/62700154
Asset: 1,666,002.00		Asset - Locn.: R23WA 13 NS		Feature Type: Splay/Swath		Area: R23WA 13 NS	
43346962	4.8.5.2 - Grass and vegetation: Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance) / 2022 / Route 23 (A45) (Provide evidence of completed works in line with ADAMR) (Area 7 - Cyclic Verge Swathe)		6 months	Job Cancelled	31/03/2022	10/08/2022	Est. 092329/62340048

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,666,002.00	Asset - Locn.: R23WA 13 NS		Feature Type: Splay/Swath		Area: R23WA 13 NS	
59072564	4.8.5.2 - Grass and vegetation: Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Verge Swathe)		1 Month	Job Cancelled	12/02/2024	30/03/2025	Est. 092329/62700154
	Asset: 1,666,003.00	Asset - Locn.: R23WA 13 NS		Feature Type: Splay/Swath		Area: R23WA 13 NS	
59072565	4.8.5.2 - Grass and vegetation: Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Verge Swathe)		1 Month	Job Cancelled	12/02/2024	30/03/2025	Est. 092329/62700154
	Asset: 1,666,004.00	Asset - Locn.: R23WA 13 NS		Feature Type: Splay/Swath		Area: R23WA 13 NS	
59072566	4.8.5.2 - Grass and vegetation: Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Verge Swathe)		1 Month	Job Cancelled	12/02/2024	30/03/2025	Est. 092329/62700154
	Asset: 1,666,005.00	Asset - Locn.: R23WA 13 OS		Feature Type: Splay/Swath		Area: R23WA 13 OS	
43350152	4.8.5.3 - Grass and vegetation: Grass cut the central reserve. Spray selective herbicide to control weeds and broad leaf species / 2022 / Route 23 (A45) (Provide evidence of completed works in line with ADAMR) (Area 7 - Cyclic Central Reserve Cut)		6 months	Substantiation Passed	31/03/2022	02/07/2022	Est. 092329/62340048

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,666,009.00		Asset - Locn.: R23WA 13 NS		Feature Type: Splay/Swath		Area: R23WA 13 NS	
59072567	4.8.5.2 - Grass and vegetation: Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2024/25 (Area 7 - Cyclic Verge Swathe)		1 Month	Job Cancelled	12/02/2024	30/03/2025	Est. 092329/62700154
Asset: 1,666,010.00		Asset - Locn.: R23WA 13 OS		Feature Type: Splay/Swath		Area: R23WA 13 OS	
59033246	4.8.3.1 - Grass and vegetation: Maintain and preserve' sight lines and stopping distance, including junctions, access points, curves, bends and central reserve. / Route 23: A45 / MRP 2024/25 (1 of 3) (Area 7 - Cyclic Visibility Cut)		1 Month	Job Cancelled	12/02/2024	31/05/2024	Est. 092329/62700082
59033410	4.8.3.1 - Grass and vegetation: Maintain and preserve' sight lines and stopping distance, including junctions, access points, curves, bends and central reserve. / Route 23: A45 / MRP 2024/25 (2 of 3) (Area 7 - Cyclic Visibility Cut)		1 Month	Job Cancelled	12/02/2024	24/10/2024	Est. 092329/62700083
Asset: 1,666,011.00		Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 OS	
60118421	4.8.3.1 - Grass and vegetation - Maintain and preserve' sight lines and stopping distance, including junctions, access points, curves, bends and central reserve. / Route 23: A45 / MRP 2025-26 (1 of 3) (East Midlands - Visibility Cut)		1 Month	Job Closed	19/03/2025	26/08/2025	Act. 092329/62700483
60118562	4.8.3.1 - Grass and vegetation - Maintain and preserve' sight lines and stopping distance, including junctions, access points, curves, bends and central reserve. / Route 23: A45 / MRP 2025-26 (2 of 3) (East Midlands - Visibility Cut)		1 Month	Job Closed	19/03/2025	26/08/2025	Act. 092329/62700483

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,666,011.00	Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 OS	
60118703	4.8.3.1 - Grass and vegetation - Maintain and preserve' sight lines and stopping distance, including junctions, access points, curves, bends and central reserve. / Route 23: A45 / MRP 2025-26 (3 of 3) (East Midlands - Visibility Cut)		1 Month	Job Closed	19/03/2025	26/08/2025	Act. 092329/62700483
	Asset: 1,666,012.00	Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 OS	
60128296	4.8.5.3a - Grass and vegetation - Grass cut the central reserve. / Route 23: A45 / MRP 2025-26 (East Midlands - Central Reserve Cuts)		1 Month	Job Closed	20/03/2025	26/08/2025	Act. 092329/62700504
60185307	4.8.5.3b - Grass and vegetation - Spray selective herbicide to control weeds and broad leaf species. / Route 23: A45 / MRP 2025-26 (East Midlands - Central Reserve Weed Spray)		1 Month	Substantiation Passed	29/03/2025	28/10/2025	Act. 092329/62700605
	Asset: 1,666,013.00	Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 OS	
60128297	4.8.5.3a - Grass and vegetation - Grass cut the central reserve. / Route 23: A45 / MRP 2025-26 (East Midlands - Central Reserve Cuts)		1 Month	Job Closed	20/03/2025	26/08/2025	Act. 092329/62700504
60185308	4.8.5.3b - Grass and vegetation - Spray selective herbicide to control weeds and broad leaf species. / Route 23: A45 / MRP 2025-26 (East Midlands - Central Reserve Weed Spray)		1 Month	Substantiation Passed	29/03/2025	28/10/2025	Act. 092329/62700605
	Asset: 1,666,014.00	Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 OS	
60128298	4.8.5.3a - Grass and vegetation - Grass cut the central reserve. / Route 23: A45 / MRP 2025-26 (East Midlands - Central Reserve Cuts)		1 Month	Job Closed	20/03/2025	26/08/2025	Act. 092329/62700504
60185309	4.8.5.3b - Grass and vegetation - Spray selective herbicide to control weeds and broad leaf species. / Route 23: A45 / MRP 2025-26 (East Midlands - Central Reserve Weed Spray)		1 Month	Substantiation Passed	29/03/2025	28/10/2025	Act. 092329/62700605

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,666,015.00		Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 OS	
60128299	4.8.5.3a - Grass and vegetation - Grass cut the central reserve. / Route 23: A45 / MRP 2025-26 (East Midlands - Central Reserve Cuts)		1 Month	Job Closed	20/03/2025	26/08/2025	Act. 092329/62700504
60185310	4.8.5.3b - Grass and vegetation - Spray selective herbicide to control weeds and broad leaf species. / Route 23: A45 / MRP 2025-26 (East Midlands - Central Reserve Weed Spray)		1 Month	Substantiation Passed	29/03/2025	28/10/2025	Act. 092329/62700605
Asset: 1,666,016.00		Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 NS	
60175506	4.8.5.2a - Grass and vegetation - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2025-26 (East Midlands - Swathe Cuts Summer)		1 Month	Job Closed	29/03/2025	01/08/2025	Act. 092329/62700584
60182787	4.8.5.2b - Grass and vegetation - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2025-26 (East Midlands - Swathe Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700600
Asset: 1,666,017.00		Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 NS	
60175507	4.8.5.2a - Grass and vegetation - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2025-26 (East Midlands - Swathe Cuts Summer)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700584

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1,666,017.00		Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 NS	
60182788	4.8.5.2b - Grass and vegetation - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2025-26 (East Midlands - Swathe Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700600
Asset: 1,666,018.00		Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 NS	
60175508	4.8.5.2a - Grass and vegetation - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2025-26 (East Midlands - Swathe Cuts Summer)		1 Month	Job Closed	29/03/2025	01/08/2025	Act. 092329/62700584
60182789	4.8.5.2b - Grass and vegetation - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2025-26 (East Midlands - Swathe Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700600
Asset: 1,666,019.00		Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 NS	
60175509	4.8.5.2a - Grass and vegetation - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2025-26 (East Midlands - Swathe Cuts Summer)		1 Month	Job Closed	29/03/2025	01/08/2025	Act. 092329/62700584
60182790	4.8.5.2b - Grass and vegetation - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2025-26 (East Midlands - Swathe Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700600

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,666,020.00	Asset - Locn.:		Feature Type: Splay/Swath		Area: R23WA 13 NS	
60175510	4.8.5.2a - Grass and vegetation - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2025-26 (East Midlands - Swathe Cuts Summer)		1 Month	Job Closed	29/03/2025	01/08/2025	Act. 092329/62700584
60182791	4.8.5.2b - Grass and vegetation - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). / Route 23: A45 / MRP 2025-26 (East Midlands - Swathe Cuts Winter)		1 Month	For Scheduling	29/03/2025	26/02/2026	Est. 092329/62700600
	Asset: 2,000,000.00	Asset - Locn.: 22575 - /A45//176.00/R/		Feature Type: Retaining Wall		Area: R23WA 13 NS	
60216904	Please carry out structures maintenance to Structure 22575 - REDDENS R/W - A45 - 176 - As per the Structures Maintenance Manual / St-MRP 2025/26		6 months	Allocated to Crew	01/04/2025	31/03/2026	Est. 092330/62402283
71133984	As per task breif attached undertake GI/A45//176.00/R/REDDENS R/W	/A45//176.00/R/	Scheme	Partial Payment Committed	11/05/2017	31/03/2018	Est. 092577/62211183
71211755	General Inspection to St.22575 REDDENS R/W	A45, km176, REDDENS R/W	Scheme	For Scheduling	23/04/2019		
	Asset: 80,000,005.00	Asset - Locn.:		Feature Type: Linear belt of trees and shrub		Area: R23WA 13 NS	
43241309	IN: Cond of Hway - Pothole - 2 large, deep, dangerous potholes between Poplar Barn and BP Garage towards W'boro 2 large, deep pot holes between Poplar Barn and White Arches Caravans/BP garage on A45 towards Wellingborough. Drivers swerving to avoid, will cause an accident, damaging to car. (Enquiry 11720276)	Nearest calculated address: A45, Wellingborough, NN29 7DL - by Poplar Barn.	* Priority - Change Me	Job Cancelled	21/02/2022		

Effective: 01/08/2025 to 01/02/2026

Display Action Officer: No

Site: 2800A45/166 - NB / END OF WELLINGBOROUGH (MD07001255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 80,000,005.00	Asset - Locn.:		Feature Type: Linear belt of trees and shrub		Area: R23WA 13 NS	
71085896	Cost Reimbursable - 1. Prune back hedge. Clear vegetation 1m from ditch. Scallop all edges. Clear any RoWs and street furniture. Thin 15% of shrubs. Remove any dead/dying trees within falling distance of road or third party property. (Overgrown by vegetation)	A45 / NB / END OF WELLINGBOROUGH ENTRY SLIP TO START OF VICTORIA PARK EXIT SLIP - MP 176/4 TO 175/4	* Priority - Change Me	Job Cancelled	12/01/2017		
	Asset: 80,000,008.00	Asset - Locn.:		Feature Type: Scattered trees		Area: R23WA 13 NS	
71085898	Cost Reimbursable - 1. Prune back hedge. Clear vegetation 1m from ditch. Scallop all edges. Clear any RoWs and street furniture. Thin 15% of shrubs. Remove any dead/dying trees within falling distance of road or third party property. (Overgrown by vegetation)	A45 / NB / END OF WELLINGBOROUGH ENTRY SLIP TO START OF VICTORIA PARK EXIT SLIP - MP 176/4 TO 175/4	* Priority - Change Me	Job Cancelled	12/01/2017		
	Asset: 80,005,000.00	Asset - Locn.:		Feature Type: TR: Tree Risk Recording		Area: R23WA 13 NS	
41734320	Small sycamore with only 2 low branches alive, rest dead. Marked with orange dot. Fell. Arisings can be chipped on site. Remove all cordwood. (TR: Dying/diseased Tree)	Little Irchester. 10m after MP 176/3. At front of plot.	6 months	Work Suspended HE	03/03/2020		
	Asset: 80,005,002.00	Asset - Locn.:		Feature Type: TR: Tree Risk Recording		Area: R23WA 13 NS	
41734325	11 dead elms all marked with orange dots. Fell. Arisings can be chipped on site, but must be clear of the ditch. Remove all cordwood. (TR: Dead Tree)	Between Little Irchester and A5001 junction. MP 175/5 + 30 in ditch line. Before 200yard countdown sign.	3 Months	Work Suspended HE	03/03/2020		
41734329	12 dead elm all marked with orange dots. Fell. Arisings can be chipped on site. Remove all cordwood. (TR: Dead Tree)	Between Little Irchester and A5001 junction. Immediately behind 300yard countdown sign, MP 175/6, for approx 20m, towards back of plot	6 months	Work Suspended HE	03/03/2020		
41734331	16 dead elms all marked with orange dots. Fell. Arisings can be chipped on site. Remove all cordwood (TR: Dead Tree)	Between Little Irchester and A5001 junction. MP 175/6 + 40, behind lamp column IR074. Middle of plot.	6 months	Work Suspended HE	03/03/2020		