

Effective: 01/12/2025 to 10/02/2026
Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Site: 3400M6/761 (MD09001469)

Locality:

Area: A9: North M6 - Link 91

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 2.00	Asset - Locn.: 3400M6/761 - M6 Junction 15. From end of Junction 15 North &			Feature Type: Two Way Single 3-Lane C/way			Area: A9: North M6 - Link 91	
Batch: 90806724 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 10/02/2026	
Batch: 90804101 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 04/02/2026	
Batch: 90804069 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 04/02/2026	
Batch: 90801746 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 27/01/2026	
Batch: 90801674 - Inspection Batch	No actionable defects found			Route: AdHoc Route			Date: 27/01/2026	
90137572	X1 pothole centre line lanes two and three May require X2 car block for M6 N/B exit and M6 S/B exit slips	27/01/2026	M6 N/B and S/B exit slip link road to jct 15 roundabout	Pavement Defect	Internal		Archived	49473269
Batch: 90799699 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 20/01/2026	
Batch: 90796632 - Inspection Batch	No actionable defects found			Route: AdHoc Route			Date: 13/01/2026	
90135861	Pothole lane 2	13/01/2026	M6 NB from top junction 15 exit A500 RBT	Pavement Defect	Internal		Archived	49471260
Batch: 90796628 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 13/01/2026	
Batch: 90796609 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 13/01/2026	
Batch: 90794139 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 06/01/2026	
Batch: 90794082 - Inspection Batch	No actionable defects found			Route: AdHoc Route			Date: 06/01/2026	
90135280	2x potholes in lane two requires filling to make safe	06/01/2026	M6 Junction 15. From end of Junction 15 North & South Exit Slip Roads to A500 Roundabout.	Pavement Defect	Internal		Committed	49470524
Batch: 90791555 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 30/12/2025	
Batch: 90790542 - Inspection Batch	No actionable defects found			Route: Route 3 New Litter Survey			Date: 23/12/2025	
Batch: 90790295 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 23/12/2025	
Batch: 90787941 - Inspection Batch	No actionable defects found			Route: Route 3, New 2025			Date: 16/12/2025	

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.	
Asset:	2.00	Asset - Locn.:	3400M6/761 - M6 Junction 15. From end of Junction 15 North & South Exit Slip Roads to A500 Roundabout.			Feature Type:	Two Way Single 3-Lane C/way	Area:	A9: North M6 - Link 91
Batch:	90782973 - Inspection Batch No actionable defects found			Route:	Route 3, New 2025			Date:	09/12/2025
Batch:	90778873 - Inspection Batch No actionable defects found			Route:	Route 3, New 2025			Date:	02/12/2025

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order		
Asset:	2.00	Asset - Locn.:	3400M6/761 - M6 Junction 15. From end of Junction 15 North & South Exit Slip Roads to A500 Roundabout.			Feature Type:	Two Way Single 3-Lane C/way	Area:	A9: North M6 - Link 91
4559984	Regime: A9 4.9.3 Litter pick paved areas, CR D: OCT - Created by Repeating Jobs Agent - Activity: Litter pick to maintain to grade A of Carriageway, paved areas and paved central reservations of motorways and APTRs SOR 4.9.3	M6 Junction 15. From end of Junction 15 North & South Exit Slip Roads to A500 Roundabout.	7 Month - Commit	Contractor Rejected	01/04/2023	19/11/2023	Est. A09002/52196422		
45611706	Regime: A9 4.9.4 Litter pick RAB,lay-bys, slips D: OCT - Created by Repeating Jobs Agent - Activity: Litter pick to maintain to grade A Motorway and APTR roundabouts and lay-bys, approach and slip roads SOR 4.9.4	M6 Junction 15. From end of Junction 15 North & South Exit Slip Roads to A500 Roundabout.	7 Month - Commit	Contractor Rejected	01/04/2023	19/11/2023	Est. A09002/52203860		
49132602	Blocked gully (DR: Blockage)	At splitter where nb exit and sb exit meet a500 junction 15	PAD: Non Safety - High	Job Closed	22/07/2021	23/07/2021	Est. D09001/62527122		
49140807	Grade C litter Verge and C/res Approx 150 yards (LI: Litter Grade C)	M6 N/B end of Jct 15 N/B and S/B exit to Jct 15 roundabout	28 days	Job Committed	17/01/2022	14/02/2022	Est. D09001/62533671		
49470524	2x potholes in lane two requires filling to make safe (Pavement Defect)	M6 Junction 15. From end of Junction 15 North & South Exit Slip Roads to A500 Roundabout.	24 Hours - Commit	Post Compl Inspection Passed	06/01/2026	11/01/2026	Act. C09002/62660206		
72830941	Regime: 4.9.4 Litter pick RAB,lay-bys, slips - Created by Repeating Jobs Agent - Litter pick to maintain to grade A Motorway and APTR roundabouts and lay-bys, approach and slip roads / MRP 25-26	N M6 R9	7 Month - Commit	Job Committed	24/03/2025	01/11/2025	Est. A09002/52370576		

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 140,001.00		Asset - Locn.: A500	Feature Type: Combined Kerb and Drainage Ch		Area: A9: North M6 - Link 91		
45609727	Regime: A9 4.3.2.1 Combined kerb, clean, jetting DUE: OCT - Created by Repeating Jobs Agent - Activity: Clearing, rodding, low pressure / high volume jetting and proving Combined Kerb and Drainage System SOR 4.3.2.1	A500	7 Month - Commit	Contractor Rejected	01/04/2023	01/11/2023	Est. A09002/52202555
72795597	Regime: 4.3.2.1 Combined kerb, clean, jetting - Created by Repeating Jobs Agent - Clearing, rodding, low pressure / high volume jetting and proving Combined Kerb and Drainage System / MRP 25-26 / NS	N M6 R9 NS	7 Month - Commit	Job Committed	23/03/2025	01/11/2025	Est. A09002/52335325
Asset: 140,002.00		Asset - Locn.: A500	Feature Type: Combined Kerb and Drainage Ch		Area: A9: North M6 - Link 91		
45609728	Regime: A9 4.3.2.1 Combined kerb, clean, jetting DUE: OCT - Created by Repeating Jobs Agent - Activity: Clearing, rodding, low pressure / high volume jetting and proving Combined Kerb and Drainage System SOR 4.3.2.1	A500	7 Month - Commit	Contractor Rejected	01/04/2023	01/11/2023	Est. A09002/52202556
72795598	Regime: 4.3.2.1 Combined kerb, clean, jetting - Created by Repeating Jobs Agent - Clearing, rodding, low pressure / high volume jetting and proving Combined Kerb and Drainage System / MRP 25-26 / NS	N M6 R9 NS	7 Month - Commit	Job Committed	23/03/2025	01/11/2025	Est. A09002/52335326
Asset: 150,001.00		Asset - Locn.:	Feature Type: Catch pit		Area: A9: North M6 - Link 91		
45599985	Regime: A9 4.3.4 Clear, empty silt from catch pit DUE: OCT - Created by Repeating Jobs Agent - Activity: Clear weed / vegetation growth around frames, clear, empty silt and debris from Catch Pits SOR 4.3.4		7 Month - Commit	Contractor Rejected	01/04/2023	01/11/2023	Est. A09002/52196423
Asset: 260,001.00		Asset - Locn.:	Feature Type: Gully		Area: A9: North M6 - Link 91		
45319754	Regime: A9: Gully clear covers - fhs BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	28/06/2022	18/08/2022	Est. A09002/52015686

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 260,001.00	Asset - Locn.:		Feature Type: Gully		Area: A9: North M6 - Link 91	
49200237	4.3.1.1 \ Gully Emptying, including clearing aprons, covers and obstructions \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Unable to Complete	27/02/2024	30/09/2024	Est. A09002/62606843
	Asset: 260,002.00	Asset - Locn.:		Feature Type: Gully		Area: A9: North M6 - Link 91	
45319755	Regime: A9: Gully clear covers - fhs BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	28/06/2022	18/08/2022	Est. A09002/52015687
49200238	4.3.1.1 \ Gully Emptying, including clearing aprons, covers and obstructions \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Unable to Complete	27/02/2024	30/09/2024	Est. A09002/62606843
	Asset: 260,003.00	Asset - Locn.:		Feature Type: Gully		Area: A9: North M6 - Link 91	
45319756	Regime: A9: Gully clear covers - fhs BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	28/06/2022	18/08/2022	Est. A09002/52015688
49200239	4.3.1.1 \ Gully Emptying, including clearing aprons, covers and obstructions \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Unable to Complete	27/02/2024	30/09/2024	Est. A09002/62606843
	Asset: 260,004.00	Asset - Locn.:		Feature Type: Gully		Area: A9: North M6 - Link 91	
45319757	Regime: A9: Gully clear covers - fhs BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	28/06/2022	18/08/2022	Est. A09002/52015689
49200240	4.3.1.1 \ Gully Emptying, including clearing aprons, covers and obstructions \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Unable to Complete	27/02/2024	30/09/2024	Est. A09002/62606843
	Asset: 260,005.00	Asset - Locn.:		Feature Type: Gully		Area: A9: North M6 - Link 91	
45319758	Regime: A9: Gully clear covers - fhs BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	28/06/2022	18/08/2022	Est. A09002/52015690
49200241	4.3.1.1 \ Gully Emptying, including clearing aprons, covers and obstructions \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Unable to Complete	27/02/2024	30/09/2024	Est. A09002/62606843
72818163	Regime: 4.3.1.2 Clear tops, aprons - Created by Repeating Jobs Agent - Activity: Clear gully aprons, covers and obstructions / MRP 25-26 / NS	N M6 R9 NS	7 Month - Commit	Work to be Rescheduled	23/03/2025	01/11/2025	Est. A09002/52357810

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 570,001.00	Asset - Locn.:		Feature Type: Longitudinal Road Marking		Area: A9: North M6 - Link 91	
49452790	IN: Spillages - DIESEL SPILLAGE IN STREAM - ENVIROMENTAL AGENCY CONCERN (Enquiry 19020163)	J15, M6 - TRENTHAM PARK GOLF CLUB	1 Hour	Job Cancelled	07/04/2025		
	Asset: 680,001.00	Asset - Locn.:		Feature Type: Sign Face		Area: A9: North M6 - Link 91	
45395839	Regime: A9: Clean Sign Faces and ref numbs Gantries BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	04/10/2022	01/12/2022	Est. A09002/52072090
	Asset: 680,002.00	Asset - Locn.:		Feature Type: Sign Face		Area: A9: North M6 - Link 91	
45395840	Regime: A9: Clean Sign Faces and ref numbs Gantries BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	04/10/2022	01/12/2022	Est. A09002/52072091
	Asset: 680,003.00	Asset - Locn.:		Feature Type: Sign Face		Area: A9: North M6 - Link 91	
45395841	Regime: A9: Clean Sign Faces and ref numbs Gantries BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	04/10/2022	01/12/2022	Est. A09002/52072092
	Asset: 680,004.00	Asset - Locn.:		Feature Type: Sign Face		Area: A9: North M6 - Link 91	
45395842	Regime: A9: Clean Sign Faces and ref numbs Gantries BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	04/10/2022	01/12/2022	Est. A09002/52072093
	Asset: 680,005.00	Asset - Locn.:		Feature Type: Sign Face		Area: A9: North M6 - Link 91	
45395843	Regime: A9: Clean Sign Faces and ref numbs Gantries BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	04/10/2022	01/12/2022	Est. A09002/52072094
49265866	4.4.1.2 \ Traffic Signs: Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Allocated to Crew	29/02/2024	30/09/2024	Est. A09002/62607283

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 680,006.00	Asset - Locn.:		Feature Type: Sign Face		Area: A9: North M6 - Link 91	
45395844	Regime: A9: Clean Sign Faces and ref numbs Gantries BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	04/10/2022	01/12/2022 Est.	A09002/52072095
	Asset: 680,007.00	Asset - Locn.:		Feature Type: Sign Face		Area: A9: North M6 - Link 91	
45395845	Regime: A9: Clean Sign Faces and ref numbs Gantries BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	04/10/2022	01/12/2022 Est.	A09002/52072096
	Asset: 680,008.00	Asset - Locn.:		Feature Type: Sign Face		Area: A9: North M6 - Link 91	
45395846	Regime: A9: Clean Sign Faces and ref numbs Gantries BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	04/10/2022	01/12/2022 Est.	A09002/52072097
49250550	4.4.1.1 \ Traffic Signs: Clean all traffic sign faces and reference numbers areas less than 5m2 \ MRP 24/25 \ North \ M6 R1 \ NS		2 Months	Unable to Complete	29/02/2024	30/09/2024 Est.	A09002/62607227
	Asset: 680,009.00	Asset - Locn.:		Feature Type: Sign Face		Area: A9: North M6 - Link 91	
45395847	Regime: A9: Clean Sign Faces and ref numbs Gantries BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	04/10/2022	01/12/2022 Est.	A09002/52072098
49250551	4.4.1.1 \ Traffic Signs: Clean all traffic sign faces and reference numbers areas less than 5m2 \ MRP 24/25 \ North \ M6 R1 \ NS		2 Months	Unable to Complete	29/02/2024	30/09/2024 Est.	A09002/62607227
	Asset: 780,001.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: A9: North M6 - Link 91	
45311709	Regime: A9: Retension Corrugated Beam Barrier BL - Created by Repeating Jobs Agent		1 Month - Commit	Contractor Rejected	27/06/2022	18/08/2022 Est.	A09002/52007647
45320497	Regime: A9: Check all Steel Road Restraint Systems BL - Created by Repeating Jobs Agent		1 Month - Commit	Contractor Rejected	28/06/2022	18/08/2022 Est.	A09002/52016429
49211066	4.2.1 \ Check all Road Restraint System,(excluding concrete barriers). \ MRP 24-25 \ North \ M6 R1 \ NS		2 Month - Commit	Job Committed	27/02/2024	30/09/2024 Est.	A09002/62606734

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,001.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: A9: North M6 - Link 91	
49227346	4.2.2.1 \ Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. RRS - Tensioned Corrugated Beam (includes barrier length, transitions and Terminals) \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Job Committed	27/02/2024	30/09/2024	Est. A09002/62606802
	Asset: 780,002.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: A9: North M6 - Link 91	
45311710	Regime: A9: Retension Corrugated Beam Barrier BL - Created by Repeating Jobs Agent		1 Month - Commit	Contractor Rejected	27/06/2022	18/08/2022	Est. A09002/52007648
45320498	Regime: A9: Check all Steel Road Restraint Systems BL - Created by Repeating Jobs Agent		1 Month - Commit	Contractor Rejected	28/06/2022	18/08/2022	Est. A09002/52016430
49212065	4.2.1 \ Check all Road Restraint System,(excluding concrete barriers). \ MRP 24-25 \ North \ M6 R1 \ OS		2 Month - Commit	Job Committed	27/02/2024	30/09/2024	Est. A09002/62606749
49227774	4.2.2.1 \ Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. RRS - Tensioned Corrugated Beam (includes barrier length, transitions and Terminals) \ MRP 24-25 \ North \ M6 R1 \ OS		2 Months	Job Committed	27/02/2024	30/09/2024	Est. A09002/62606816

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 780,003.00		Asset - Locn.:	Feature Type: Safety Barrier (Steel)		Area: A9: North M6 - Link 91		
45320499	Regime: A9: Check all Steel Road Restraint Systems BL - Created by Repeating Jobs Agent		1 Month - Commit	Contractor Rejected	28/06/2022	18/08/2022	Est. A09002/52016431
45395848	Regime: A9: Retension Corrugated Beam Barrier BL - Created by Repeating Jobs Agent		1 Month - Commit	Job Cancelled	04/10/2022	01/12/2022	Est. A09002/52072099
49212066	4.2.1 \ Check all Road Restraint System,(excluding concrete barriers). \ MRP 24-25 \ North \ M6 R1 \ OS		2 Month - Commit	Job Committed	27/02/2024	30/09/2024	Est. A09002/62606749
Asset: 780,004.00		Asset - Locn.:	Feature Type: Safety Barrier (Steel)		Area: A9: North M6 - Link 91		
45311711	Regime: A9: Retension Corrugated Beam Barrier BL - Created by Repeating Jobs Agent		1 Month - Commit	Contractor Rejected	27/06/2022	18/08/2022	Est. A09002/52007649
45320500	Regime: A9: Check all Steel Road Restraint Systems BL - Created by Repeating Jobs Agent		1 Month - Commit	Contractor Rejected	28/06/2022	18/08/2022	Est. A09002/52016432
49211067	4.2.1 \ Check all Road Restraint System,(excluding concrete barriers). \ MRP 24-25 \ North \ M6 R1 \ NS		2 Month - Commit	Job Committed	27/02/2024	30/09/2024	Est. A09002/62606734

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 780,004.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: A9: North M6 - Link 91	
49227347	4.2.2.1 \ Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. RRS - Tensioned Corrugated Beam (includes barrier length, transitions and Terminals) \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Job Committed	27/02/2024	30/09/2024	Est. A09002/62606802
	Asset: 780,005.00	Asset - Locn.:		Feature Type: Safety Barrier (Steel)		Area: A9: North M6 - Link 91	
45311712	Regime: A9: Retension Corrugated Beam Barrier BL - Created by Repeating Jobs Agent		1 Month - Commit	Contractor Rejected	27/06/2022	18/08/2022	Est. A09002/52007650
45320501	Regime: A9: Check all Steel Road Restraint Systems BL - Created by Repeating Jobs Agent		1 Month - Commit	Contractor Rejected	28/06/2022	18/08/2022	Est. A09002/52016433
49211068	4.2.1 \ Check all Road Restraint System,(excluding concrete barriers). \ MRP 24-25 \ North \ M6 R1 \ NS		2 Month - Commit	Job Committed	27/02/2024	30/09/2024	Est. A09002/62606734
49227348	4.2.2.1 \ Tighten or replace screws and bolts and re-tension Road Restraint System requiring re-tensioning. RRS - Tensioned Corrugated Beam (includes barrier length, transitions and Terminals) \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Job Committed	27/02/2024	30/09/2024	Est. A09002/62606802

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,030,001.00	Asset - Locn.: M6/15/W/004/1		Feature Type: Lighting Unit			Area: A9: North M6 - Link 91
49309207	4.4.1.2 \ Traffic Signs: Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Job Cancelled	13/03/2024		
49309218	4.4.1.2 \ Traffic Signs: Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Unable to Complete	13/03/2024	30/09/2024	Est. A09002/62607318
	Asset: 1,030,004.00	Asset - Locn.: A500/15/W/06/1		Feature Type: Lighting Unit			Area: A9: North M6 - Link 91
49309208	4.4.1.2 \ Traffic Signs: Clean all traffic sign faces and reference numbers areas greater than or equal to 5m2 \ MRP 24-25 \ North \ M6 R1 \ NS		2 Months	Job Cancelled	13/03/2024		
	Asset: 1,030,017.00	Asset - Locn.: M6/15/W/005/1		Feature Type: Lighting Unit			Area: A9: North M6 - Link 91
49437995	Area 9 Rotated Bracket (Area 9 Rotated Bracket)		SL: Light Out 6 Months	Job Cancelled	01/12/2024		
	Asset: 1,030,018.00	Asset - Locn.: M6/15/W/005/2		Feature Type: Lighting Unit			Area: A9: North M6 - Link 91
49437982	Area 9 Not on 6 Months (Area 9 Not on 6 Months)		SL: Light Out 6 Months	Job Cancelled	01/12/2024		
	Asset: 1,100,006.00	Asset - Locn.: A500/15/W/06/1 - 3400M6/761 - NB - 3 Lanes - One Way Single		Feature Type: Lighting Column			Area: A9: North M6 - Link 91
45602729	Regime: A9 4.8.4.1 Illumination not obscured DUE: OCT - Created by Repeating Jobs Agent - Activity: Ensure illumination/lumination from lighting is not obscured SOR 4.8.4.1	3400M6/761 - NB - 3 Lanes - One Way Single Carriageway	7 Month - Commit	Contractor Rejected	01/04/2023	01/11/2023	Est. A09002/52198569
	Asset: 1,100,007.00	Asset - Locn.: M6/15/W/005/1 - 3400M6/761 - NB - 3 Lanes - One Way Single		Feature Type: Lighting Column			Area: A9: North M6 - Link 91
45602831	Regime: A9 4.8.4.1 Illumination not obscured DUE: OCT - Created by Repeating Jobs Agent - Activity: Ensure illumination/lumination from lighting is not obscured SOR 4.8.4.1	3400M6/761 - NB - 3 Lanes - One Way Single Carriageway	7 Month - Commit	Contractor Rejected	01/04/2023	01/11/2023	Est. A09002/52198635

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,100,008.00	Asset - Locn.: M6/15/W/005/2 - 3400M6/761 - NB - 3 Lanes - One Way Single		Feature Type: Lighting Column			Area: A9: North M6 - Link 91
45602871	Regime: A9 4.8.4.1 Illumination not obscured DUE: OCT - Created by Repeating Jobs Agent - Activity: Ensure illumination/lumination from lighting is not obscured SOR 4.8.4.1	3400M6/761 - NB - 3 Lanes - One Way Single Carriageway	7 Month - Commit	Contractor Rejected	01/04/2023	01/11/2023	Est. A09002/52198640
	Asset: 1,100,009.00	Asset - Locn.: M6/15/W/006/1 - 3400M6/761 - NB - 3 Lanes - One Way Single		Feature Type: Lighting Column			Area: A9: North M6 - Link 91
45602872	Regime: A9 4.8.4.1 Illumination not obscured DUE: OCT - Created by Repeating Jobs Agent - Activity: Ensure illumination/lumination from lighting is not obscured SOR 4.8.4.1	3400M6/761 - NB - 3 Lanes - One Way Single Carriageway	7 Month - Commit	Contractor Rejected	01/04/2023	01/11/2023	Est. A09002/52198641
	Asset: 1,100,010.00	Asset - Locn.: M6/15/W/004/1 - 3400M6/761 - NB - 3 Lanes - One Way Single		Feature Type: Lighting Column			Area: A9: North M6 - Link 91
45602873	Regime: A9 4.8.4.1 Illumination not obscured DUE: OCT - Created by Repeating Jobs Agent - Activity: Ensure illumination/lumination from lighting is not obscured SOR 4.8.4.1	3400M6/761 - NB - 3 Lanes - One Way Single Carriageway	7 Month - Commit	Contractor Rejected	01/04/2023	01/11/2023	Est. A09002/52198642
	Asset: 1,666,001.00	Asset - Locn.:		Feature Type: Splay/Swath			Area: A9: North M6 - Link 91
45599850	Regime: A9 4.8.4.2 Maintain technology access DUE: OCT - Created by Repeating Jobs Agent - Activity: Remove obstructions and/or maintain vegetation to facilitate safe access for inspection and maintenance of technology equipment. SOE 4.8.4.2		7 Month - Commit	Job Cancelled	01/04/2023	01/11/2023	Est. A09002/52196288
45758473	Regime: A9 4.8.3.1 Sight lines, stopping distances DUE:MAY - Created by Repeating Jobs Agent - Activity: Maintain and preserve' sight lines and stopping distance, including junctions, access points, curves, bends and central reserve. SOR 4.8.3.1		1 Month - Commit	Contractor Rejected	13/04/2023	01/06/2023	Est. A09002/52246911

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,666,001.00	Asset - Locn.:		Feature Type: Splay/Swath		Area: A9: North M6 - Link 91	
45803334	Regime: A9 4.8.3.1 Sight lines, stopping distances DUE:JUN - Created by Repeating Jobs Agent - Activity: Maintain and preserve' sight lines and stopping distance, including junctions, access points, curves, bends and central reserve. SOR 4.8.3.1		1 Month - Commit	Contractor Rejected	04/05/2023	01/07/2023	Est. A09002/52258524
45875590	Regime: A9 4.8.3.1 Sight lines, stopping distances DUE:SEP - Created by Repeating Jobs Agent - Activity: Maintain and preserve' sight lines and stopping distance, including junctions, access points, curves, bends and central reserve. SOR 4.8.3.1		1 Month - Commit	Contractor Rejected	04/08/2023	01/10/2023	Est. A09002/52272820
72696645	Regime: 4.8.3.1 Sight lines, stopping distances - Created by Repeating Jobs Agent - Maintain and preserve' sight lines and stopping distance, including junctions, access points, curves, bends and central reserve. / MRP 25-26 / NS	N M6 R9 1 of 3 NS	2 Month - Commit	Work to be Rescheduled	19/03/2025	01/06/2025	Est. A09002/52294114
73071157	Regime: 4.8.3.1 Sight lines, stopping distances - Created by Repeating Jobs Agent - Maintain and preserve' sight lines and stopping distance, including junctions, access points, curves, bends and central reserve. / MRP 25-26 / NS	N M6 R9 M 3 of 3 NS	7 Month - Commit	Job Committed	22/05/2025	01/11/2025	Est. A09002/52445638
	Asset: 1,666,002.00	Asset - Locn.:		Feature Type: Splay/Swath		Area: A9: North M6 - Link 91	
45599280	Regime: A9 4.8.5.2 Verge swathe cut DUE: OCT - Created by Repeating Jobs Agent - Activity : Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance). SOR 4.8.5.2		7 Month - Commit	Contractor Rejected	01/04/2023	01/11/2023	Est. A09002/52195981

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,666,002.00	Asset - Locn.:		Feature Type: Splay/Swath		Area: A9: North M6 - Link 91	
45599851	Regime: A9 4.8.4.2 Maintain technology access DUE: OCT - Created by Repeating Jobs Agent - Activity: Remove obstructions and/or maintain vegetation to facilitate safe access for inspection and maintenance of technology equipment. SOE 4.8.4.2		7 Month - Commit	Job Cancelled	01/04/2023	01/11/2023	Est. A09002/52196289
72830159	Regime: 4.8.5.2 Verge swathe cut - Created by Repeating Jobs Agent - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance) / MRP 25-26 / NS	N M6 R9 NS	7 Month - Commit	Allocated to Crew	24/03/2025	01/11/2025	Est. A09002/52369795
73125082	Regime: 4.8.5.2B Vertical verge swathe cut - Created by Repeating Jobs Agent - Undertake 2m wide swathe cut of all highway verges to ensure strip remains unobstructed by vegetation throughout the year (in addition to visibility splay maintenance) / Vertical cut / 25-26 / NS	N M6 R9 NS	6 Month - Commit	Allocated to Crew	16/10/2025	31/03/2026	Est. A09002/52453040
	Asset: 1,666,003.00	Asset - Locn.:		Feature Type: Splay/Swath		Area: A9: North M6 - Link 91	
45449367	Regime: A9 4.8.3.3 Sign and signal visibility cut Due: SEP - Created by Repeating Jobs Agent - Activity: Maintain and preserve road users' visibility of road traffic signs and signals SOR 4.8.3.3		6 Month - Commit	Contractor Rejected	20/03/2023	01/10/2023	Est. A09002/52097857
45599852	Regime: A9 4.8.4.2 Maintain technology access DUE: OCT - Created by Repeating Jobs Agent - Activity: Remove obstructions and/or maintain vegetation to facilitate safe access for inspection and maintenance of technology equipment. SOE 4.8.4.2		7 Month - Commit	Job Cancelled	01/04/2023	01/11/2023	Est. A09002/52196290

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1,666,003.00	Asset - Locn.:		Feature Type: Splay/Swath		Area: A9: North M6 - Link 91	
72795656	Regime: 4.8.3.3 Sign and signal visibility cut - Created by Repeating Jobs Agent - Maintain and preserve road users' visibility of road traffic signs and signals / MRP 25-26 / NS	N M6 R9 NS	7 Month - Commit	Allocated to Crew	23/03/2025	01/11/2025	Est. A09002/52335384
	Asset: 1,696,001.00	Asset - Locn.:		Feature Type: Woodland		Area: A9: North M6 - Link 91	
49295057	4.8.15 \ Woodlands and trees, including veteran trees: Maintain habitat integrity, including removal of scrub encroachment. \ MRP 24-25 \ North \ M6 R1		2 Months	Job Committed	11/03/2024	28/02/2025	Est. A09002/62607939

Effective: 01/12/2025 to 10/02/2026
 Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 2,000,003.00	Asset - Locn.: STR_2443 - 15/M6//246.20/Q/1		Feature Type: Bridge And Large Culvert		Area: A9: North M6 - Link 91	
49162535	Bridge routine maintenance, to include (where applicable) removing graffiti; removing undesirable vegetation, e.g. that blocks drainage, can cause structural damage or restricts access; removing debris, bird droppings and other detritus that blocks drainage, promotes corrosion or other deterioration, or presents a health risk to inspectors or others; clearing and ensuring correct operation of drain holes, drainage channels and drainage systems; repairing gap sealant to movement joints; checking operation of flap valves and greasing where required; checking and tightening where necessary any loose nuts and bolts to expansion joints, parapet supports and gantry holding down assemblies, replacing nuts and bolts where appropriate; removing general dirt and debris from bearings, where appropriate, cleaning sliding and roller surfaces if accessible and re-greasing, following any additional advice contained in the bearing manufacturer's instructions; checking (and rectifying where necessary) seating of drainage gratings or covers, replacing any missing or defective items; checking, cleaning and replacing pedestrian security measures (e.g. mirrors, handrails, nonslip Surfaces; unprotected edges); checking for scour damage around training works; checking holding down assemblies; Any Health and Safety Risks and before and after photos at each work site for all appropriate maintenance items. Reminder - review AAP (if applicable) before commencing work	STR_2443 15/M6//246.20/Q/1 Hanchurch Service Culvert	8 Month - Commit	Unable to Complete	25/11/2022	30/07/2023	Est. D09002/62302531

Effective: 01/12/2025 to 10/02/2026
Site: 3400M6/761 (MD09001469)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
---------	-------------	----------	----------	------------	---------	------------	-------------